

Diplomat Parts Pte Ltd (Co.Reg.No:196400304H)

209 Pandan Gardens

Singapore 609339

Tel: 65684556/65684555 Fax: 65691056 Email: angela.chua@cyclecarriage.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF24B00000800	Date of Loss:	03/10/2024
Vehicle Reg. No.:	SMQ7309X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CYCLE & CARRIAGE LEASING PTE LTD		
Make/Model:	KIA CERATO, 1.6 (A)	Vehicle Reg. Date:	29/11/2019
Vehicle Colour:	WHITE	Chassis No:	KNAF1416MK5044613
Engine No:	G4FGKH737376		
Odometer:	62583 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	DIPLOMAT PARTS PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	3,758.70
Miscellaneous Items	290.00
Labour	1,480.00
Paintwork Labour	400.00
Towing	0.00
Gross Total (S\$)	5,928.70
+ GST 9.00% (S\$)	533.58
Nett Amount (S\$)	6,462.28

This claim is handled by: VIKNESWARAN NAIDU AYAVOO

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DETAILS

ence

Source:	MRM-SG	Version:	1.0 (Last Synchronised: 08 Oct 2024)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Diplomat Parts Pte Ltd/SMQ7309X/08/10/2024 14:05		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*COVER-FR BUMPER <i>repair</i>	0.00	0.00	*433.00 F
2	1		*GRILLE-FRONT BUMPER <i>ca</i>	0.00	0.00	*171.00 F
3	1		*GRILLE ASSY-RADIATOR	0.00	0.00	*189.00 F
4	1		*GARNISH-RADIATOR GRILLE <i>X</i>	0.00	0.00	*33.00 F
5	1		*ABSORBER-FRONT BUMPER ENERGY <i>?</i>	0.00	0.00	*55.00 F
6	1		*STIFFNER-FR BPR LWR <i>X</i>	0.00	0.00	*75.00 F
7	1		*BEAM COMPLETE-FR BUMPER <i>X</i>	0.00	0.00	*324.00 F
8	1		*CARRIER ASSY-FRONT END MODULE <i>X</i>	0.00	0.00	*439.00 F
9	1		*BLOWER ASSY <i>?</i>	0.00	0.00	*461.00 F
10	1		*RADIATOR ASSY <i>bt</i>	0.00	0.00	*510.00 F
11	1		*CONDENSER ASSY-COOLER <i>bt</i>	0.00	0.00	*439.00 F
12	1		*GUARD-AIR,LH <i>?</i>	0.00	0.00	*19.00 F
13	1		*GUARD-AIR,RH <i>?</i>	0.00	0.00	*19.00 F
14	1		*PANEL ASSY-UNDER COVER <i>?</i>	0.00	0.00	*99.00 F
15	1		*DUCT ASSY-EXTENSION <i>X</i>	0.00	0.00	*108.00 F
16	1		*DUCT ASSY-AIR <i>X</i>	0.00	0.00	*43.00 F

F=Franchise part.

Sub Total (S\$)	3,417.00
+ Margin on L,N Items 10.00% (S\$)	341.70
Total Parts (S\$)	3,758.70

Diplomat Parts Pte Ltd/SMQ7309X/08/10/2024 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Particulars	Amount
<u>Miscellaneous Items</u>	
1 SUNDRIES	20.00
1 SUPPLY COOLANT	80 100.00
3 1 SUPPLY NUMBER PLATE	35 50.00
4 1 TOP UP A/C GAS	100 120.00
Sub Total (\$\$)	290.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY FRT BUMPER, HOOD	New	200 400.00
<u>Labour Items</u>			
2	TOTAL LABOUR PANEL FOR RENEW FRT BUMPER, LWR BUMPER, REPAIR HOOD, AND DAMAGED PARTS	New	220 600.00
3	MECHANICAL LABOUR FOR RENEW CONDENSER, RADIATOR AND ETC	New	220 440.00
4	CHECK DIAGNOSIS AND ELECTRICAL CHECK	New	220.00
5	CHECK WIRING	New	40 80.00
6	REMOVE AND REFIT SENSOR	New	X 80.00
Gross Labour Cost (\$\$)			1,880.00

Diplomat Parts Pte Ltd/SMQ7309X/08/10/2024 14:05. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS
 < END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Handwritten notes:
 Pass
 Hp 90010068
 5 days
 P/P
 excess: 1000
 Repair
 Reg 54 paint
 09/10/24