

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

Tel: 63896111
Attn: Motor Claim Department

Fax: 6221033

Your Ref No: TP 0624-8086
Claim Type: Third Party
Accident Date: 20 June 2024
TP Veh Reg No: SMZ8543G

not Authorized
for
moras
1/7/24
1/5 \$400
shop. Affix
4 days

Estimate No: EST1511417
Date: 21 Jun 2024
Policy No: P10230449R04
Veh Reg No: SMD8786M
Make/Model: NISSAN NOTE 1.2 CVT
Chassis No: JN1TAAE12Z0982110
Engine No: HR12200405J
Reg. Date: 10 Sep 2018

Estimate Repair Cost to Vehicle No: SMD8786M

Description	Unit Price	Quantity	List Price SGD	Amount SGD
Nett				
List Price				
1 TAILGATE <i>DO/3 ref</i>	1,133.20	1 PC	1,133.20	✓
2 TAILGATE HINGE - LH/RH <i>17</i>	63.10	2 PC	126.20	X
3 TAILGATE ABSORBER - LH/RH <i>17</i>	220.10	2 PC	440.20	X
4 TAILGATE "NOTE" WORDINGS <i>ref</i>	104.00	1 PC	104.00	✓
5 TAILGATE NISSAN LOGO <i>ref</i>	72.00	1 PC	72.00	✓
6 TAILGATE OUTER GARNISH <i>17</i>	284.40	1 PC	284.40	X
7 TAILGATE NUMBER PLATE LAMP - LH/RH <i>17</i>	67.60	2 PC	135.20	X
8 TAILGATE LOCK <i>su</i>	148.30	1 PC	148.30	X
9 TAILGATE WEATHERSTRIP <i>su</i>	78.90	1 PC	78.90	X
10 TAILGATE GLASS MOULDING <i>ref</i>	182.30	1 PC	182.30	✓
11 REAR BUMPER <i>DO/3 ref</i>	512.20	1 PC	512.20	✓
12 REAR BUMPER REFLECTOR - LH/RH <i>17</i>	61.90	2 PC	123.80	X
13 REAR BUMPER LOWER SPOILER <i>no. ref 10</i>	450.00	1 PC	450.00	✓
14 REAR BUMPER FOAM <i>71.7</i>	139.60	1 PC	139.60	✓
15 REAR BUMPER REINFORCEMENT BRACKET - LH/RH <i>ref</i>	69.30	2 PC	138.60	✓
16 REAR END PANEL <i>DO/3 ref</i>	616.10	1 PC	616.10	✓
17 REAR END PANEL TOP GARNISH <i>su</i>	76.70	1 PC	76.70	X
18 TAILLAMP - RH <i>su</i>	485.20	1 PC	485.20	✓
19 TAILLAMP CLIPS - RH <i>17</i>	5.00	2 PC	10.00	X
			5,256.90	
		Less 10%	-525.69	4,731.21
Special Net				
20 REAR BUMPER SENSOR	200.00	1 PC	200.00	X
21 SEALANT <i>rear wind screen</i>	20.00	2 PC	40.00	✓
22 SPONGE TAPE <i>rear wind screen</i>	20.00	1 PC	20.00	✓
				260.00
Labour				
23 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	850.00	1 JOB	850.00	600
24 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	800.00	1 JOB	800.00	700
25 TO CHECK WIRING-	50.00	1 JOB	50.00	20
26 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00	50
27 TO REMOVE, REPLACE REAR BUMPER SENSOR-	80.00	1 JOB	80.00	30
28 TO TRANSFER TAILGATE FITTINGS-	80.00	1 JOB	80.00	50
29 TO TUFFKOTE-	60.00	1 JOB	60.00	50
30 TO REMOVE, REFIT REAR GLASS-	150.00	1 JOB	150.00	120
				2,220.00

7-3833-2
10%
344588
512888
4103

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Total	7,211.21
Add GST @ 9%	649.01
Total Amount Payable SGD	<u>7,860.22</u>

SINGAPORE DOLLAR SEVEN THOUSAND EIGHT HUNDRED SIXTY AND CENTS TWENTY TWO ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE