

SERVE YOU MOTOR PTE LTD

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: elainesyms@gmail.com

*Not Authorized
Return By paint
5 day*

Ins: China Taiping Insurance (Singapore) Pte Ltd

Owner: Chan Bus Chartered

Registration no. : PC 1122 U / TOYOTA HIACE SUPER GL DARK PRIME 2.8 AUTO

Accident Date : 03/10/2024

Date : 4-Oct-24

Quotation No. : 11221003

S/N	Qty	Particulars	Amount
-----	-----	-------------	--------

LIST ITEMS

1	1	Rear tailgate	<i>M</i> 2,357.34 ✓
2	1	Rear tailgate inner lock	<i>n</i> 769.12 X
3	1	Rear tailgate outer handle	<i>n</i> 185.00 X
4	1	Rear tailgate inner trimboard	<i>n</i> 588.90 X
5	1	Rear tailgate inner rubber	<i>n</i> 454.00 X
6	1	Rear tailgate windscreen moulding	<i>nsp</i> 188.80 X
7	1	Rear taillamp RH	<i>CM</i> 488.60 ✓
8	1	Rear bumper	<i>Bu/mg ori</i> 670.12 ✓
9	1	Rear bumper stepboard panel	<i>n</i> 384.00 X
10	2	Rear bumper retainer \$138 each	<i>n</i> 276.00 X
11	1 set	Rear bumper clip	<i>n</i> 56.00 ✓
12	1	Rear bumper reinforcement	<i>nsp</i> 389.00 X
13	1	Rear end panel	<i>n</i> 860.00 X
			7,666.88
			1,916.72
			5,750.16

Less 25%

SPECIAL NETT ITEMS

2	1	Rear windscreen glass	<i>Shatter</i> 1,598.26 ✓
3	1	Rear windscreen glass sealant	<i>n</i> 80.00 <i>400n</i>
4	1	"70km/h" sticker	<i>n</i> 8.50 ✓
5	1 set	Reverse sensor	<i>n</i> 380.00 X
6	1 set	Rear camera	<i>Shatter</i> 480.00 <i>350n</i>
8	1	Emergency Door sticker	<i>n</i> 80.00 ✓
9	1	Rear tailgate "Toyota" Hiace" logo	<i>n</i> 158.00 ✓
10	1	Rear number plate	<i>n</i> 60.00 X
			2844.76

LABOUR & MISC CHARGES

1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts	Acknowledged by Repairer Signature: Date:	800.00 500l
2	To remove and refit camera to facilitate the repair.		150.00 60l
3	To remove and refit rear windscreen to facilitate the repair.		150.00 120l
4	To remove and refit rear cover compartment, third light for facilitate repair.		180.00 80l
5	Supply spray paint material and necessary items on rear accident portion.		950.00 800l
	TOTAL		2,230.00

Total Parts and Labour Cost of Repair**\$10,824.92**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company