



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100171/Anh3e2
75 BRAS BASAH ROAD	Date:	25/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 861S	Veh. Inspected	SNL 9182U
Policy No.	-	Coverage	0
Claim No.	MT/1298656-002	Excess	\$0.00
Assign From	CHARLOTTE CHEW	Assign Date	08/10/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA HYBRID	C.C	1490
Engine No.	M15AY665297	Year of Reg.	15/08/2023
Chassis No.	MXPL101050530	Colour	WHITE
Odometer	121085 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/60 R15	FARROAD	6
L/H Front Tyre	195/60 R15	FARROAD	6
R/H Rear Tyre	195/60 R15	FARROAD	6
L/H Rear Tyre	195/60 R15	FARROAD	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/10/2024	Inspection Date	09/10/2024 (14:27)
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 13 Working Days