

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24100172/Anh3m4	
	75 BRAS BASAH ROAD NCOME CENTRE SINGAPORE 189557		Date:	22/11/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLZ 2474Z	Veh. Inspected	SNJ 712K	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1298831-001	Excess	\$0.00	
	Assign From	RAJESWARY	Assign Date	08/10/2024	
2.	Vehicle Details				
	Make & Model	TOYOTA CAMRY ASCENT SPORT 2.5 HYBRID CVT	c.c	2487	
	Engine No.	A25A0A31020	Year of Reg.	30/03/2021	
	Chassis No.	JTNB23HK003076032	Colour	WHITE	
	Odometer	27727 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	255/40R18	MICHELIN	6	
	L/H Front Tyre	255/40R18	MICHELIN	6	
	R/H Rear Tyre	255/40R18	MICHELIN	6	
	L/H Rear Tyre	255/40R18	MICHELIN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS. General Information					
5.	Accident Date 05/10/2024 Inspection Date 09/10/2024 (14:49)				
	Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a.		Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair