

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAW LEE TING
772 WOODLANDS DR 60 #07-164
SINGAPORE 730772

TP INC
Veron.

Contact : 92479406

TAX INVOICE

Repair Code : CLM16438

Date in : 02/10/2024

Vehicle Num. : SLC6768X

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1656629/HRA2275603A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehid</i>	1	860.40	<i>755</i> 860.40 ✓
REAR BUMPER INNER ANTENNA SENSOR <i>Can't</i>	1	72.00	72.00 -
REAR BUMPER REFLECTOR L/R <i>2</i>	2	66.90	133.80 +
REAR BUMPER REINFORCEMENT <i>1</i>	1	746.20	746.20 +
REAR BUMPER SIDE RETAINER L/R <i>2</i>	2	42.80	85.60 +
REAR BUMPER SPONGE <i>1</i>	1	152.90	152.90 ✓
REAR BUMPER TOW HOOK COVER <i>Dehid</i>	1	30.00	30.00 ✓
REAR END PANEL <i>Dehid</i>	1	573.40	573.40 -
REAR END PANEL INNER TOP GARNISH <i>1</i>	1	74.90	74.90 +
REAR TAILGATE <i>1</i>	1	3306.00	3,306.00 +
REAR TAILGATE 'LOGO' EMBLEM <i>1</i>	1	70.00	70.00 +
REAR TAILGATE 'QASHQAI' EMBLEM <i>1</i>	1	101.90	101.90 +
REAR TAILGATE MECHANISM LOCK <i>1</i>	1	205.50	205.50 +
REAR TAILGATE WEATHER STRIP <i>1</i>	1	198.40	198.40 +
Subtotal before discount			6,611.00
Percentage discount 10%			661.10
Sub-total 1			5,949.90
REAR BUMPER CLIPS - SET <i>1</i>	1	80.00	80.00 ✓ <i>30</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAW LEE TING
772 WOODLANDS DR 60 #07-164
SINGAPORE 730772

Contact : 92479406

TAX INVOICE

Repair Code : CLM16438

Date in : 02/10/2024

Vehicle Num. : SLC6768X

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1656629/HRA2275603A

REAR BUMPER REVERSE SENSOR (4 EYES) - SET	2nd	1	380.00	380.00	280
REAR END PANEL INNER TOP GARNISH CLIPS - SET	3rd	1	30.00	30.00	+
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	3rd	1	50.00	50.00	+
Subtotal before discount				540.00	
Percentage discount 0%				0.00	
Sub-total 2				540.00	
Parts-total				6,489.90	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

80.00 50

To remove, reinstall tailgate windscreen

150.00 +

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80.00 40

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

600.00 400

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

600.00 400

To apply anti-rust chemical on repaired and replaced panel.

80.00 60

To remove, reinstall tailgate mechanism and check for function

80.00 +

Labour Total

1,670.00

Parts & Labour Total

8,159.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*** This is a computer-generated document which requires no signature. ***

page 2

Admin Li
1/s 09/10/24

overly

total: 2684.97
4/s: 2.1K ✓