

ASS. REC. BY:

REF:

1021

CS/FCI 24100177/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$175k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

W064836

Yr Regn:

02, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

m, Corolla Mix

Make:

Isuzu

CYH

c.c

15681

Colour

Multi Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

65495

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JAL CYH 52TN 7000098

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

Puranze 295/80R22.5

R:

Joyroad

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

J J mm

L/Bal.

J J mm

D.O.A.

4/10/24

Rear

R/Bal.

66 55mm

L/Bal.

66 55mm

D.O.I.

11/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

EU not ready

15/10/24

11pm @ 3400h Carlu

(Red. \$6103.81, 64%)

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TSR AUTOMOTIVE PTE LTD
HANDPHONE 93825367

Date : 10 Oct 2024

QUOTATION - THIRD PARTY CLAIM

M/S FIRST CAPITAL INSURANCE

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 4 Oct 2024

VEH. No WD 6483 G / CYH52TM

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : INVCOME INSURANCE

QTY	ITEM	AMOUNT	
1	FRONT BUMPER <i>1800</i>	\$ <i>R</i> 3,852.00	✓
1	FRONT BUMPER OUTER RIM LH (CHROME) <i>385</i>	\$ <i>mi</i> 480.00	✓
1	HEADLAMP LH <i>980.60</i>	\$ <i>cm</i> 2,485.00	✓
1	SIGNAL LAMP LH <i>415</i>	\$ <i>cm</i> 1,120.00	✓
1	DOOR LAMP LH <i>180</i>	\$ <i>cm</i> 498.00	✓
1	STEP PANEL GARNISH LH	\$ <i>in</i> 475.60	X
1	STEP PANEL LH	\$ <i>n</i> 388.00	X
TOTAL PARTS :		\$ 9,298.60	
LESS 15% <i>10</i>		\$ 1,394.79	
TOTAL LIST PARTS :		\$ 7,903.81	
TOTAL PARTS PRICE :		\$ 7,903.81	
AMOUNT BRING FORWARD :		\$ 7,903.81	
Labour charges to replace parts , remove refix , align adjust etc		\$ 800.00	<i>400/</i>
Check wiring system, forcus lamp		\$ 120.00	<i>20/</i>
To do anti rust		\$ <i>nn</i> 80.00	X
To do spray painting on accident affected area		\$ 600.00	<i>500/</i>
TOTAL LABOUR :		\$ 1,600.00	
GRAND TOTAL PARTS AND LABOUR :		\$ 9,503.81	

Not Authorized
L1Pnp @ 3400/4
Resurvey After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days