

(08/11/13) wef

ASS. REC. BY: MARUS

REF:

C5/11/24100178/Unp3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ DD / ☐ TR / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SLA 74245

at Workshop m/s My auto 10an.

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: ?

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$24k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA ☒ REV / REP. / 24 HRS

751d  
Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LIA 12020

Date / Time \_\_\_\_\_ Action / Instruction Dep 13k

Veh No: SLA 74245 Yr Regn: 15/03/16

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or CA /

Make: Honda vazei c.c. 1496

Colour Blue A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading 133180 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: \_\_\_\_\_

C/No: R411110576

Gen. Cond: ☐ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☐ Nil / ☐ S/Bm / ☐ STD A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or \_\_\_\_\_

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 07/10/24 D.O.I. 10/10/24

Survey held at \_\_\_\_\_

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

015 dnf

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1) \_\_\_\_\_  
Date/Time, File Return to?

☐ : Final Report

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_ S + RS \_\_\_\_ SI

Photos

Others

TOTAL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	751D

### Vehicle Details

Vehicle No.:	SLA7424S
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2024
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4030579
Chassis No.:	RU111110576
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,749.00
Original Registration Date:	15 Mar 2016
First Registration Date:	15 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$9,749.00 $\downarrow$ 874

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2026
PARF Rebate Amount:	\$5,361.00

### Intended COE Rebate Details

COE Expiry Date:	14 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$6,659.00
Total Rebate Amount:	\$12,020.00

### Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 10 Oct 2024

OK



Search Results for honda vezel



**Honda Vezel 1.5A X** **\$24,800** \$13,700 /yr 21-Mar-2016 (1yr 5mths COE left) 123,000 km

**Honda Sensing** **Instl. \$1,121** 1,496 cc 1 Owner

**Cheapest In The Market With Guaranteed Buyback At \$10,000 At End Of COE.** Depreciation At \$9000+ Only. Rare 1 Owner With Low Mileage Proves Its Non Phv With Proofs. Best Mid Sized SUV. Spacious, Reliable And Low In Consumption And Maintenance. Accident In Original Paintwork Still Intact. Clean And Beautiful Interior. Sheltered Parked Daily. Sheltered Parked Daily. Non Smoker. Full In Hse/bank Loan

BuySafe

Posted 08-Oct-2024

☐ Compare



**Honda Vezel** **\$34,800** \$12,660 /yr 27-Dec-2016 (2yrs 2mths COE left) 98,000 km 1,496 cc

**1.5A X** **Instl. \$1,025** 1 Owner

One of the most popular SUV in Singapore, experience the perfect blend of style, comfort, and efficiency with this stunning 1 owner, well-maintained unit. Spacious interior features a flexible seating arrangement and allows easy configuration to accommodate for passengers or cargo. Impressive fuel efficiency with safety features making it a reliable/popular choice. Contact us today for viewing!

Warranty

**SG Car Choice Pte Ltd** | Posted 07-Oct-2024

☐ Compare



**Honda Vezel** **\$21,800** \$13,100 /yr 04-Feb-2016 (1yr 3mths COE left) 80,000 km 1,496 cc

**1.5A X** **Instl. \$1,122** 1 Owner

1 Owner, Excellent Condition And Well Kept By Previous Owner! Loan Available! Trade In Welcome! Act Fast And Call Us Now To Fix An Appointment To View This Stunning Unit!

**Zenith Automobile** | Posted 07-Oct-2024

☐ Compare

## Handy Tools

[View All](#)

[Loan Calculator](#)



[Used Car Depre Finder](#)



[Bidded Carplate](#)



[COE Renewal](#)



[Petrol Discount](#)



[My Shortlist](#)



[Compare](#)

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3158/10/24

Your Ref:

Date: 8th OCT 2024

MR KOH YOK HUAT  
BLK 381A, #10-1529  
YISHUN RING RD,  
SINGAPORE 761381

Not Authorised  
10/10/24  
2/8

Excess \$600?

Take the After 14 days  
3 days

Estimate cost of repair to HONDA VEZEL 1.5 (A) SUV - SLA 7424 S

1 pc front bumper	DP	\$ 947.30	✓
10 pcs front bumper clips	6\$ 3.90	39.00	✓
1 pc front bumper o/s side retainer		29.50	X
1 pc front bumper o/s top retainer		48.50	?
1 pc front o/s fender		431.20	X
1 pc front o/s fender wheel garnish		150.60	✓
10 pcs front o/s fender wheel garnish clips	6\$ 3.90	39.00	X
		\$ 1,685.10	
	Less 20%	\$ 337.02	
		\$ 1,348.08	

To wiring check up for affected wiring system.

50.00 20

To check & adjust front wheel alignment & balancing.

120.00 7

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s fender, front bumper reinforcement & necessary parts, to weld, renew & align above parts.

650.00 300

To putty & respray painting on all affected accident parts.

700.00 500

To respray Tuff-Kote on all affected accident parts.

50.00 X

\$ 2,918.08

=====

Dollars : Two Thousand Nine Hundred Eighteen And Cents Eight Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: