

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3158/10/24

Your Ref: _____

Date: 8th OCT 2024

MR KOH YOK HUAT
BLK 381A, #10-1529
YISHUN RING RD,
SINGAPORE 761381

Not Authorised
10/10/24
2/5

Excess 600?

Calculation after 3 days

Estimate cost of repair to HONDA VEZEL 1.5 (A) SUV - SLA 7424 S

1 pc front bumper	DA	\$ 947.30	✓
10 pcs front bumper clips	6\$ 3.90	39.00	✓
1 pc front bumper o/s side retainer	11	29.50	X
1 pc front bumper o/s top retainer		48.50	?
1 pc front o/s fender	2	431.20	X
1 pc front o/s fender wheel garnish	150	150.60	✓
10 pcs front o/s fender wheel garnish clips	6\$ 3.90	39.00	X
		\$ 1,685.10	
	Less 20%	\$ 337.02	
		\$ 1,348.08	

To wiring check up for affected wiring system.

50.00 20

To check & adjust front wheel alignment & balancing.

120.00 ?

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s fender, front bumper reinforcement & necessary parts, to weld, renew & align above parts.

650.00 300

To putty & respray painting on all affected accident parts.

700.00 500

To respray Tuff-Kote on all affected accident parts.

11 50.00 X

\$ 2,918.08

=====

Dollars : Two Thousand Nine Hundred Eighteen And Cents Eight Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3158/10/24 Your Ref: _____ Date: 10th Oct 2024

MR KOH YOK HUAT
BLK 381A, #10-1529
YISHUN RING RD, S(761381)

Supplementary Bill for HONDA VEZEL 1.5 (A) SUV- SLA 7424 S

1 pc front bumper lower spoiler skirt garnish	\$ 382.50	gra
	Less 20% \$ 76.50	
	<u>\$ 306.00</u>	
	=====	

Dollars : Three Hundred And Six Dollars Only.

HUP MOTOR TRADING & SERVICE

.....
