

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd
6 Raffles Quay
#22-00
Singapore 048580

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 10 Oct 2024

Preliminary Advice

Vehicle No	: SLA7424S	Accident Date	: 07/10/2024
Make	: HONDA VEZEL	Policy No.	: D22MPC0002323
Assignment Date	: 09/10/2024	Excess	: S\$0.00
Date of Inspection	: 10/10/2024	Est. Duration of Repair	: 3
Inspection At	: HUP MOTOR TRADING & SERVICE (HQ) BLK 9004 TAMPINES STREET 93, #01-120 SINGAPORE 528838		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,224.08
Revised Amount	:S\$	2,035.52
Check Items (Estimated)	:S\$	158.80
Total	:S\$	2,194.32
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	24,000.00
COE / PARF Rebate	:S\$	12,020.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,980.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.