

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	. INSURANCE (S) PL	Ref:	CS/AGI24100180/Uqp3m4	
	(BUDGET DIRECT	INSURANCE)	Date:	21/10/2024	
	190 CLEMENCEAU	J AVENUE #03-01 PPING CENTRE SINGAPORE 239924	Code:	AGI	
1.	ON OAL ONE OFFICE	Policy Particulars :- 1			
- 1.	Insured Veh.	SFZ 1130T	Veh. Inspected	SCZ 6866G	
	Policy No.	-	Coverage	0	
	Claim No.	C10032140/MC	Excess	\$0.00	
	Assign From	MONICA CHUNG	Assign Date	09/10/2024	
2.	Assignition	Vehicle		00/10/2024	
L .	Make & Model	MAZDA CX-5 2.0 AT	C.C	1998	
	Engine No.	PE31366131	Year of Reg.	09/03/2020	
	Chassis No.	JM6KF2W7AK0324364	Colour	SILVER	
	Odometer	32732 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/65R17	YOKOHAMA	6	
	L/H Front Tyre	225/65R17	YOKOHAMA	6	
	R/H Rear Tyre	225/65R17	YOKOHAMA	6	
	L/H Rear Tyre	225/65R17	YOKOHAMA	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	03/10/2024	Inspection Date	14/10/2024	
	Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883			
5a.	Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
,					

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days