

not Approved
in menu
14/10/24
d/s \$3600
3 days

Regn No : SCZ6866G

Chassis Number: JM6KF2W7AK0324364

Make & Model: Mazda CX-5 2.0

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
List Items:				
1	Rear tailgate <i>no / set</i>	1	\$ 1,790.00	\$ 1,790.00
2	Rear tailgate lock <i>su</i>	1	\$ 282.00	\$ 282.00 X
3	Rear tailgate lock catch <i>u</i>	1	\$ 68.00	\$ 68.00 X
4	Rear tailgate inner pull handle <i>u</i>	1	\$ 45.00	\$ 45.00 X
5	Rear tailgate inner trim <i>u</i>	1	\$ 422.00	\$ 422.00 X
6	Rear tailgate emblem - MAZDA <i>u</i>	1	\$ 55.00	\$ 55.00 X
7	Rear tailgate emblem - CX-5 <i>u</i>	1	\$ 52.00	\$ 52.00 X
8	Rear tailgate emblem -Skyactiv Technology <i>u</i>	1	\$ 82.00	\$ 82.00 X
9	Rear number plate lamp <i>u</i>	2	\$ 41.60	\$ 83.20 X
10	Rear windscreen moulding <i>u</i>	1	\$ 105.00	\$ 105.00
11	Rear taillamp <i>u</i>	2	\$ 1,446.00	\$ 2,892.00 X
12	Rear taillamp panel housing <i>u</i>	2	\$ 375.00	\$ 750.00 X
13	Rear bumper <i>de/grease</i>	1	\$ 1,478.00	\$ 1,478.00 <i>12x2.88</i>
14	Rear bumper reinforcement <i>But</i>	1	\$ 652.00	\$ 652.00 <i>596.58</i>
15	Rear bumper lower garnish <i>u</i>	1	\$ 285.00	\$ 285.00 X
16	Rear bumper reflector LH/RH <i>u</i>	2	\$ 254.00	\$ 508.00 X
17	Rear bumper side retainer LH/RH <i>u</i>	2	\$ 30.00	\$ 60.00 X
18	Rear bumper tow cover <i>u</i>	2	\$ 35.00	\$ 70.00 X
19	Rear bumper side garnish <i>u</i>	2	\$ 50.00	\$ 100.00 X
20	Rear end panel <i>R</i>	1	\$ 719.00	\$ 719.00 X
21	Rear end panel garnish <i>u</i>	1	\$ 87.00	\$ 87.00 X
			Sub-total	\$ 10,585.20
			Less 20.00%	\$ 2,117.04
			Total	\$ 8,468.16

Special Nett Items:				
1	Rear windscreen sealant <i>u</i>	1	\$ 90.00	\$ 90.00 <i>40</i>
2	Rear inner trim clip <i>u</i>	8	\$ 4.50	\$ 36.00 X
3	Rear taillamp side holder clip <i>u</i>	4	\$ 10.50	\$ 42.00 X
4	Rear bumper clip <i>u</i>	8	\$ 5.50	\$ 44.00 X
5	Rear number plate with holder <i>u</i>	1	\$ 50.00	\$ 50.00 X
6	Rear bumper reverse sensor <i>u</i>	2	\$ 230.00	\$ 460.00 X
			S/Nett Items Total	\$ 722.00

Labour Charge Items:				
1	To checking electrical wiring and check functions		\$ 60.00	<i>20</i>
2	To remove and refix rear windscreen glass		\$ 180.00	<i>120</i>
3	To transfer rear tailgate parts		\$ 150.00	<i>50</i>
4	To remove and refix inner trim		\$ 100.00	<i>X</i>
5	To refix and replace reverse sensors and reverse camera		\$ 160.00	<i>30</i>
6	To respray undercoating/rust proofing		\$ 100.00	<i>30</i>
7	To respray painting & etc		\$ 1,050.00	<i>700</i>
8	Panel beating, cut, weld, remove and replacing above parts		\$ 900.00	<i>540</i>
			Labour Charge Total	\$ 2,700.00

LKK Auto Consultants hence notify

the Repairer of the following:

- Estimate Parts & Labour**
- To resurvey and/or spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand total \$ 11,890.16

P-3734.44
202
2987.55
40
1490
4517.55
3614