

KIM SIA AUTO SERVICE

No. 2 KAKI BUKIT AVENUE

IX: 67475363H/P: 84843837 (AH LONG)

Not Authorised
der
moray
6/11/24
2/s \$5000
whph. Atwrap -
3 days

Vehicle No: SMT3960A

Model & Make : TOYOTA HARRIER PREMIUM 2

Vehicle Parts

Front Portion

Front Bumper	De/torn	944.02	2,104.70 ✓
Front Bumper Guard	cut		291.00 ✓
Front Bumper Moulding	neu		249.67 ✓
Radiator Grille	cut		1,479.68 ✓
Lower No. 1 Radiator Grille	^^		305.00 X
Hood to Radiator Grille Seal	^^		146.91 X
Radiator Grille Bracket (R)	^^		112.84 X
Radiator Grille Bracket (L)	^^		111.52 X
Front Bumper Side Retainer (L & R)	^^		239.70 X
Front Bumper Energy Absorber	^^		182.44 X
Front Bumper Reinforcement (Impact Bar)	^^		655.00 X
No. 2 Front Bumper Side Retainer (L & R)	^^		245.95 X
LH Front Bumper Energy Absorber	^^		112.19 X
RH Front Bumper Energy Absorber	^^		112.19 X
Front Headlamp Assy (L & R)	o/s holder cno	4345.12	8,690.24 1p ✓
Fog Lamp Assy (L)	^^		442.51 X
Fog Lamp Assy (R)	^^		437.47 X
Hood Lock Assy	^^		125.80 X

Rear Portion (25%) **\$16,044.81**
Less : 20% \$3,208.96
Rear Portion **\$12,835.85**

Special Nett Items

1/2ef Front Bumper Cover Rivet(s)	neu	70.00	30 s/n
Front Bumper Cover Screw(s)	^^	35.00	X
Front Bumper Bolt(s)	^^	20.00	X
Front Bumper Nut(s)	^^	20.00	X
Front Bumper Support Rail Nut(s)	^^	30.00	X
Front Headlamp Screw(s)	^^	35.00	X
Front Headlamp Clip(s)	^^	35.00	X
Front Bumper No. 1 Clip(s)	^^	30.00	X
Front Bumper No.1 Screw(s)	^^	20.00	X
Common Screw(s)	^^	30.00	X
Common Bolt(s)	^^	30.00	X
Front License Plate	bmf	80.00	
Front License Plate Holder		80.00	40 s/n

Special Net**\$515.00****Labour****ELECTRICAL MISCELLANEOUS**

Housing (ECU)	150.00	X
To Rectify & Remove and/or Replace Damaged Wiring (Front)	150.00	
To Remove & Replace Damaged Wiring (Front)	120.00	
To Replace and/or Repack Wiring Setups From ECU	120.00	
To Diagnose Post Replacement Configuration Of New Wiring At	180.00	X
To Dismantle & Identify Damaged Headlamp & Misc. Wiring (Front)	250.00	X

SPRAY PAINTING

To Spray Vehicle Body Replace Body Panels, Damaged Panels and	1,500.00	400
---	----------	-----

LABOUR MISCELLANEOUS

To Provide Professional Labour, Workmanship to Replace, Repair,	1,600.00	300
To Remove & Replace Front Bumper, Re-align Bodywork Fitment	120.00	
To Dismantle & Replace and/or Repair Front Bumper Assembly	180.00	
To Dismantle, Replace and/or Repair Front Bumper, Grille Portion (E	240.00	
To Dismantle, Replace and/or Repair Front Bumper, Grille Portion (I	240.00	
To Dismantle, Replace Front Head Lamps	120.00	

Labour Total**\$4,970.00****ESTIMATES PARTS & LABOUR GRAND TOTAL****\$18,320.85**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7309.49
252
5-482.12
70
720
6272.12
202
5017.