

not Arbon
9/10/24
1/c 3400
Take ph. All 1/2
4 days

Claim Type: Third Party Claim
 Attn: MS First Capital Insurance Limited
 Motor Claims Department
 Owner: KEH GIM HWEE, PATRICK
 DOA: 8 Oct 2024

REPAIR ESTIMATE
 Date: 9 Oct 2024
 Vehicle Num: SLD565Z
 Make/Model: HONDA VEZEL 1.5
 Chassis #: RU11112577
 Engine #: L15B4032583
 Yr. Of Manu: 2016

No.	Description	Qty	U/P	Amt
<u>Section: LIST ITEMS</u>				
1	Rear Bumper <i>DD</i>	1	S\$ 1029.60	S\$ 1,029.60 <i>762.00</i>
2	Rear Bumper Retainer LH/RH <i>17</i>	2	S\$ 38.50	S\$ 77.00 <i>X</i>
3	Rear Bumper Lower Cover (UPPER) <i>2</i>	1	S\$ 650.10	S\$ 650.10 <i>X</i>
4	Rear Bumper Lower Cover (LOWER) <i>2</i>	1	S\$ 580.10	S\$ 580.10 <i>X</i>
5	Rear Bumper Reflector LH/RH <i>17</i>	2	S\$ 270.80	S\$ 541.60 <i>X</i>
6	Rear Bumper Reinforcement <i>NS</i>	1	S\$ 689.70	S\$ 689.70 <i>X</i>
7	Rear Bumper Sponge <i>NS</i>	1	S\$ 325.70	S\$ 325.70 <i>X</i>
8	Bootlid <i>DD</i>	1	S\$ 1550.20	S\$ 1,550.20 <i>1099.20</i>
9	Bootlid Lock	1	S\$ 356.10	S\$ 356.10 <i>280.40</i>
10	Bootlid Lock Catch	1	S\$ 86.40	S\$ 86.40 <i>DD</i>
11	Bootlid "VEZEL" Emblem	1	S\$ 63.20	S\$ 63.20 <i>1M</i>
12	Bootlid "LOGO" Emblem	1	S\$ 58.70	S\$ 58.70 <i>1M</i>
13	Bootlid Inner Trim Board	1	S\$ 385.20	S\$ 385.20 <i>5M</i>
14	Bootlid Garnish	1	S\$ 289.50	S\$ 289.50 <i>1M</i>
15	Bootlid Rubber	1	S\$ 185.20	S\$ 185.20 <i>1M</i>
16	Bootlid Lamp RH	1	S\$ 297.60	S\$ 297.60 <i>17</i>
17	Taillamp RH	1	S\$ 398.50	S\$ 398.50 <i>17</i>
18	Rear Number Plate Lamp LH/RH	2	S\$ 68.50	S\$ 137.00 <i>17</i>
19	Rear Bumper Corner Panel LH/RH	2	S\$ 382.20	S\$ 764.40 <i>17</i>
20	Rear End Panel	1	S\$ 738.20	S\$ 738.20 <i>517</i>
21	Rear End Panel Top Garnish	1	S\$ 148.20	S\$ 148.20 <i>Ref / DD</i>
22	Rear Reverse Sensor	1	S\$ 310.20	S\$ 620.40 <i>1M</i>
23	Rear Antenna Sensor	1	S\$ 128.10	S\$ 128.10 <i>Ref</i>
24	Rear Spare Tyre Panel	1	S\$ 887.50	S\$ 887.50 <i>8M</i>
25	Rear Spare Tyre Top Board	1	S\$ 559.60	S\$ 559.60 <i>2M</i>
26	Rear Spare Tyre Panel Sponge	1	S\$ 343.90	S\$ 343.90 <i>17</i>
27	Exhaust Pipe	1	S\$ 1980.70	S\$ 1,980.70 <i>2</i>
			Amt S\$	13,872.40
DISCOUNT			20% S\$	2,774.48
Subtotal S\$				11,097.92



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

No.	Description	Qty	U/P	Amt
Section: Special Nett				
28	Rear Bumper Clips - Set	1	S\$ 80.00 S\$	80.00 30
29	Rear Bootlid Inner Trim Clips - Set	1	S\$ 80.00 S\$	80.00 30
30	Rear End Panel Top Garnish cCips - Set	1	S\$ 80.00 S\$	80.00 X
31	Rear Number Plate W Holder	1	S\$ 120.00 S\$	120.00 X
32	Rear End Panel Seaalnt	1	S\$ 60.00 S\$	60.00 240
Amt S\$				420.00

No.	Description	Qty	U/P	Amt
Section: LABOUR				
26	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		S\$	1,500.00 600
27	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		S\$	1,500.00 700
28	CHECK THE WIRING AND LIGHTING SYSTEM ON AFFECTED AND CONSISTENT AREAS		S\$	80.00 20
29	APPLY RUST COATING CHEMICAL ON AFFECTED AND CONSISTENT AREAS AND PANELS		S\$	120.00 30
30	TRANSFER AND REPLACE BOOTLID INNER MECHANISM TO ASSIST REPIRT		S\$	80.00 60
31	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR		S\$	80.00 40
32	TO REMOVE, REINSTALL UPHOLSTERY, CUSHION-SEAT, TRIM GARNISH, TRIM LINER CARPET.		S\$	120.00 60
Amt S\$				3480.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LIST ITEMS Subtotal: S\$ 11,097.92
SPECIAL NETT ITEMS Subtotal S\$ 420.00
LABOUR Subtotal: S\$ 3,480.00
Total: S\$ 14,997.92

Joo Hak Kee Auto Pte. Ltd.

Acknowledged by Repairer
Signature:
Date:

P- 3055.2
202
244416
300
1510
425416
3403.

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE₃