



Final Report

Estimate No. : **b1 71378**
Date Estimated : **02/10/2024**
Prepared By : **Jack Ng Guo Ming**

Page No. :

- ESTIMATE REPAIR FOR -

Loo Kwai Xiang, Vincent (Lu Guixiang)
Blk 373 Clementi Avenue 4
#06-198

Singapore 120373

- ACCOUNT - 144674

ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SGN615U	WBA32GM0905Z95677	23/07/2024	X2 sDrive16i SAC	4493

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front LH wheel arch cover trim include making good the front LH fender and carrying out other necessary repairs caused by the accident	850.00		850.00	
To respray front LH wheel arch cover and front LH fender	1,628.00		1,628.00	
To check electrical wiring system and lightings at the LH section for proper function	177.00		177.00	
To replace wheel rim include balancing (x1)	94.00		94.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (x1)	531.00		531.00	
Sundries	80.00		80.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 8JX20 MIDNIGHT GREY	2,248.10	1.00	0.00	2,248.10
FRT LH WHEEL ARCH COVER TRIM MSP GR	300.75	1.00	0.00	300.75

SUPPLEMENTARY ITEMS

Total Labour :	3,360.00
Total Parts :	2,548.85
Total Labour & Parts (before GST) :	5,908.85
Deduction for Excess :	
Total Repair Costs less Excess:	5,908.85
GST @9%:	531.80
Grand Total :	6,440.65

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

