

ASSIGNMENT

Front: _____ Date: _____
 Est: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy: _____
 Claims: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: Tereh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNK2024U Yr Regn: 2023, March
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Nissan Serena CC 1198
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 57867 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JNIEBAC2720001675
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R16
 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kapsen

Front: _____ Rear: _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 09/10/24

Survey held at Bifrost
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Check</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes</u>
	<u>1st Survey : No</u>
	<u>MV : 170K</u>
	<u>PV : 107.5K</u>
	<u>Nett : 62.5K</u>
We will be advising our principal a cost of repair of LS \$5,800.00 with 6 days of repair (red, \$18235.38, 75%)	

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

1) Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Form used:

Report Form used:

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SNK 2024U**
Made : Nissan
Model : Serena 1.2L Highway
Chassis No : JN1EBAC27Z0001675

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Tailgate <i>Dented</i>	1	\$ 1,938.80	\$ ✓ 1,938.80
2	Rear Upper Tailgate with Windscreen Glass <i>new</i>	1	\$ 4,468.40	\$ ✗ 4,468.40
3	Rear Tailgate Outer Chrome Garnish <i>new</i>	1	\$ 887.30	\$ ✗ 887.30
4	Rear Tailgate "Serena" Outer Garnish <i>new</i>	1	\$ 887.30	\$ ✗ 887.30
5	Rear Tailgate Emblem <i>new</i>	1	\$ 97.00	\$ ✗ 97.00
6	Rear Tailgate "Highway Star" Emblem <i>new</i>	1	\$ 101.00	\$ ✓ 101.00
7	Rear Tailgate "E-Power" Emblem <i>new</i>	1	\$ 101.00	\$ ✓ 101.00
8	Rear Tailgate Lock Assembly <i>new</i>	1	\$ 222.30	\$ ✓ 222.30
9	Rear Tailgate Weatherstrip <i>new</i>	1	\$ 118.50	\$ ✗ 118.50
10	Rear Tailgate Inner Trim Board <i>new</i>	1	\$ 361.10	\$ ✓ 361.10
11	Rear Bumper <i>Dented</i>	1	\$ 1,574.00	\$ ✓ 1,574.00
12	Rear Bumper Side Retainer RH <i>new</i>	1	\$ 36.20	\$ ✗ 36.20
13	Rear Bumper Side Retainer LH <i>new</i>	1	\$ 36.20	\$ ✗ 36.20
14	Rear Bumper Garnish RH <i>new</i>	1	\$ 97.00	\$ ✗ 97.00
15	Rear Bumper Garnish LH <i>new</i>	1	\$ 97.00	\$ ✗ 97.00
16	Rear Taillamp Assembly RH <i>new</i>	1	\$ 623.90	\$ ✗ 623.90
17	Rear Taillamp Lower Garnish RH <i>new</i>	1	\$ 428.90	\$ ✗ 428.90
18	Rear Taillamp Assembly LH <i>new</i>	1	\$ 623.90	\$ ✗ 623.90
19	Rear Taillamp Lower Garnish LH <i>new</i>	1	\$ 428.90	\$ ✓ 428.90
20	Rear End Panel <i>Dented</i>	1	\$ 239.60	\$ ✓ 239.60
21	Rear End Panel Top Garnish <i>new</i>	1	\$ 78.30	\$ ✓ 78.30
22	Rear Fender RH <i>new</i>	1	\$ 1,392.00	\$ ✗ 1,392.00
23	Rear Fender Inner Trim Board RH <i>new</i>	1	\$ 710.10	\$ ✗ 710.10
24	Rear Fender Inner Cowling RH <i>new</i>	1	\$ 38.70	\$ ✗ 38.70
25	Rear Fender LH <i>new</i>	1	\$ 1,392.00	\$ ✗ 1,392.00
26	Rear Fender Inner Trim Board LH <i>new</i>	1	\$ 710.10	\$ ✓ 710.10
27	Rear Fender Inner Cowling LH <i>new</i>	1	\$ 38.70	\$ ✗ 38.70

Parts Sub Total :	\$	17,728.20
10% Discount	\$	1,772.82
PARTS TOTAL :	\$	15,955.38

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate <i>new</i>	1	\$ 50.00	\$ + 50.00
2	Rear Bumper Clips - Set <i>new</i>	1	\$ 50.00	\$ 30 50.00
3	Rear Tailgate Inner Trim Board Clips - Set <i>new</i>	1	\$ 50.00	\$ 30 50.00
4	Rear End Panel Top Garnish Clips - Set <i>new</i>	1	\$ 50.00	\$ 20 50.00
5	Rear Fender Inner Trim Board Clips - Set <i>new</i>	1	\$ 50.00	\$ 30 50.00
6	Rear Fender Inner Cowling Clips - Set <i>new</i>	1	\$ 50.00	\$ + 50.00
7	Rear Tailgate Sealant <i>new</i>	1	\$ 150.00	\$ + 150.00
8	Rear End Panel Sealant <i>new</i>	1	\$ 150.00	\$ 60 150.00
9	Rear Fender RH Sealant	1	\$ 150.00	\$ + 150.00
10	Rear Fender LH Sealant	1	\$ 150.00	\$ + 150.00
11	Rear Fender RH Glass Sealant	1	\$ 150.00	\$ + 150.00
12	Rear Fender LH Glass Sealant	1	\$ 150.00	\$ + 150.00
13	Rear Tailgate Windscreen Glass Sealant <i>new</i>	1	\$ 150.00	\$ + 150.00
14	Rear Bumper Reverse Sensor - Set <i>new</i>	1	\$ 350.00	\$ 20 350.00
15	Rear Tailgate Reverse Camera - Set <i>new</i>	1	\$ 550.00	\$ + 550.00
SPECIAL NETT TOTAL :				\$ 2,250.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 700 2,000.00
2	To Spray Paint Affected Areas	\$ 700 1,800.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Rear Tailgate Components	\$ 60 150.00
5	To Remove & Refix Rear Tailgate Windscreen Glass	\$ + 150.00
6	To Remove & Refix Rear Fender Glass RH	\$ + 150.00
7	To Remove & Refix Rear Fender Glass LH	\$ + 150.00
8	To Remove & Refix Rear Bumper Reverse Sensors	\$ 50 150.00
9	To Remove & Refix Rear Tailgate Reverse Camera	\$ 50 150.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 60 150.00
11	To Remove & Refix Fuel Tank to facilitate repairs	\$ + 150.00
12	To apply anti rust on affected parts	\$ 60 150.00
13	To Conduct Water Leak Test	\$ + 100.00
14	To Send for Diagnostic and Reset Control Unit. Programming & Calibrat	\$ + 480.00
LABOUR TOTAL :		\$ 5,830.00

Handwritten signature
 L/S 09/10/24
 06 Days

PARTS TOTAL :	\$	15,955.38
SPECIAL NETT TOTAL :	\$	2,250.00
LABOUR TOTAL :	\$	5,830.00
GRAND TOTAL :	\$	24,035.38

Adrian G
 2/s 09/10/24
 06 Days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____