

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____

Date of Survey : _____

Date of ReSurvey: _____

Contacts : _____

Vehicle Nos : **SNK 2024U**

Made : Nissan

Model : Serena 1.2L Highway

Chassis No : JN1EBAC27Z0001675

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Tailgate <i>Dented</i>	1	\$ 1,938.80	\$ 1,938.80
2	Rear Upper Tailgate with Windscreen Glass <i>new</i>	1	\$ 4,468.40	\$ 4,468.40
3	Rear Tailgate Outer Chrome Garnish <i>new</i>	1	\$ 887.30	\$ 887.30
4	Rear Tailgate "Serena" Outer Garnish <i>new</i>	1	\$ 887.30	\$ 887.30
5	Rear Tailgate Emblem <i>new</i>	1	\$ 97.00	\$ 97.00
6	Rear Tailgate "Highway Star" Emblem <i>new</i>	1	\$ 101.00	\$ 101.00
7	Rear Tailgate "E-Power" Emblem <i>new</i>	1	\$ 101.00	\$ 101.00
8	Rear Tailgate Lock Assembly <i>new</i>	1	\$ 222.30	\$ 222.30
9	Rear Tailgate Weatherstrip <i>new</i>	1	\$ 118.50	\$ 118.50
10	Rear Tailgate Inner Trim Board <i>new</i>	1	\$ 361.10	\$ 361.10
11	Rear Bumper <i>Dented</i>	1	\$ 1,574.00	\$ 1,574.00
12	Rear Bumper Side Retainer RH <i>new</i>	1	\$ 36.20	\$ 36.20
13	Rear Bumper Side Retainer LH <i>new</i>	1	\$ 36.20	\$ 36.20
14	Rear Bumper Garnish RH <i>new</i>	1	\$ 97.00	\$ 97.00
15	Rear Bumper Garnish LH <i>new</i>	1	\$ 97.00	\$ 97.00
16	Rear Taillamp Assembly RH <i>new</i>	1	\$ 623.90	\$ 623.90
17	Rear Taillamp Lower Garnish RH <i>new</i>	1	\$ 428.90	\$ 428.90
18	Rear Taillamp Assembly LH <i>new</i>	1	\$ 623.90	\$ 623.90
19	Rear Taillamp Lower Garnish LH <i>new</i>	1	\$ 428.90	\$ 428.90
20	Rear End Panel <i>Dented</i>	1	\$ 239.60	\$ 239.60
21	Rear End Panel Top Garnish <i>new</i>	1	\$ 78.30	\$ 78.30
22	Rear Fender RH <i>new</i>	1	\$ 1,392.00	\$ 1,392.00
23	Rear Fender Inner Trim Board RH <i>new</i>	1	\$ 710.10	\$ 710.10
24	Rear Fender Inner Cowling RH <i>new</i>	1	\$ 38.70	\$ 38.70
25	Rear Fender LH <i>new</i>	1	\$ 1,392.00	\$ 1,392.00
26	Rear Fender Inner Trim Board LH <i>new</i>	1	\$ 710.10	\$ 710.10
27	Rear Fender Inner Cowling LH <i>new</i>	1	\$ 38.70	\$ 38.70

Parts Sub Total :	\$	17,728.20
10% Discount	\$	1,772.82
PARTS TOTAL :	\$	15,955.38

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate <i>new</i>	1	\$ 50.00	\$ + 50.00
2	Rear Bumper Clips - Set <i>new</i>	1	\$ 50.00	\$ 30 50.00
3	Rear Tailgate Inner Trim Board Clips - Set <i>new</i>	1	\$ 50.00	\$ 30 50.00
4	Rear End Panel Top Garnish Clips - Set <i>new</i>	1	\$ 50.00	\$ 20 50.00
5	Rear Fender Inner Trim Board Clips - Set <i>new</i>	1	\$ 50.00	\$ 30 50.00
6	Rear Fender Inner Cowling Clips - Set <i>new</i>	1	\$ 50.00	\$ + 50.00
7	Rear Tailgate Sealant <i>new</i>	1	\$ 150.00	\$ + 150.00
8	Rear End Panel Sealant <i>new</i>	1	\$ 150.00	\$ 60 150.00
9	Rear Fender RH Sealant	1	\$ 150.00	\$ + 150.00
10	Rear Fender LH Sealant	1	\$ 150.00	\$ + 150.00
11	Rear Fender RH Glass Sealant	1	\$ 150.00	\$ + 150.00
12	Rear Fender LH Glass Sealant	1	\$ 150.00	\$ + 150.00
13	Rear Tailgate Windscreen Glass Sealant <i>new</i>	1	\$ 150.00	\$ + 150.00
14	Rear Bumper Reverse Sensor - Set <i>new</i>	1	\$ 350.00	\$ 20 350.00
15	Rear Tailgate Reverse Camera - Set <i>new</i>	1	\$ 550.00	\$ + 550.00
SPECIAL NETT TOTAL :				\$ 2,250.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 700 2,000.00
2	To Spray Paint Affected Areas	\$ 700 1,800.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Rear Tailgate Components	\$ 60 150.00
5	To Remove & Refix Rear Tailgate Windscreen Glass	\$ + 150.00
6	To Remove & Refix Rear Fender Glass RH	\$ + 150.00
7	To Remove & Refix Rear Fender Glass LH	\$ + 150.00
8	To Remove & Refix Rear Bumper Reverse Sensors	\$ 50 150.00
9	To Remove & Refix Rear Tailgate Reverse Camera	\$ 50 150.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 60 150.00
11	To Remove & Refix Fuel Tank to facilitate repairs	\$ + 150.00
12	To apply anti rust on affected parts	\$ 60 150.00
13	To Conduct Water Leak Test	\$ + 100.00
14	To Send for Diagnostic and Reset Control Unit. Programming & Calibrat	\$ + 480.00
LABOUR TOTAL :		\$ 5,830.00

Handwritten signature
 L/S 09/10/24
 06 Days

PARTS TOTAL :	\$	15,955.38
SPECIAL NETT TOTAL :	\$	2,250.00
LABOUR TOTAL :	\$	5,830.00
GRAND TOTAL :	\$	24,035.38

Adrian G
 2/s 09/10/24
 06 Days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date: