



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
ATTN: Jasmine Lok

INV No. AC2600389
INV Date 16/01/2026
Reference CD/LPC24100189/Epa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMB 1306Y
Insured Veh. XD 8188J
Claim No. 23/24/24/VC05/030001
Policy No. Z23VC05021316
Accident Date 03/10/2024
Inspection Date 10/10/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: Jasmine Lok		Ref: CD/LPC24100189/Epa3q2(N) Date: 16/01/2026 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 8188J	Veh. Inspected	SMB 1306Y
Policy No.	Z23VC05021316	Coverage (\$)	0.00
Claim No.	23/24/24/VC05/030001	Excess (\$)	0.00
Assign From	JASMINE LOK	Assign Date	10/10/2024
2. Vehicle Particulars & Condition			
Make & Model	MAN NL320F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WMAA22ZZ0D7001726	Colour	MULTI COLOUR
Odometer	120819 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	5 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	5 mm
R/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm
L/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/10/2024	Inspection Date	10/10/2024
Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1306Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	MIRROR VIEW FRONT RH ,FOR MAN	BROKEN	1,244.90	1,244.90
	LESS 10% DISCOUNT		-124.49	-124.49
			1,120.41	1,120.41
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS .		265.00	132.50
	TOWING CHARGE.		200.00	200.00
			465.00	332.50
	GRAND TOTAL		1,585.41	1,452.91
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CD/LPC24100189/Epa3q2(N)

CHEN TSUE YEE

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y




PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y




PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y




PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y



PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y



PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMB 1306Y

