

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM CHIN PENG
BLK 419 PASIR RIS DR 6 #08-273
SINGAPORE 510419

Contact : 97825573

TAX INVOICE

Repair Code : CLM18404

Date in : 09/10/2024

Vehicle Num. : SMV2504E

Model : HONDA CIVIC 1.6 VTI CVT

Chassis/Eng# : MRHFC5650LT000290/R16B25520391

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	949.70	✓ 949.70
FRONT RH DOOR CHECKER <i>new</i>	1	49.20	+ 49.20
FRONT RH DOOR GLASS REGULATOR WITH MOTOR <i>new</i>	1	359.00	✓ 359.00
FRONT RH DOOR HINGE (LOWER) <i>new</i>	1	49.20	+ 49.20
FRONT RH DOOR HINGE (TOP) <i>new</i>	1	49.20	+ 49.20
FRONT RH DOOR INNER TRIM BOARD <i>new</i>	1	495.70	✓ 495.70
FRONT RH DOOR MECHANISM LOCK <i>new</i>	1	181.20	✓ 181.20
FRONT RH DOOR OUTER CHROME MOULDING <i>Dented</i>	1	80.50	✓ 80.50
FRONT RH DOOR OUTER HANDLE <i>new</i>	1	103.20	+ 103.20
FRONT RH DOOR SIDE MIRROR <i>new</i>	1	407.20	✓ 407.20
FRONT RH DOOR SIDE MIRROR COVER <i>new</i>	1	78.10	+ 78.10
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	78.50	✓ 78.50
FRONT RH DOOR WEATHER STRIP LOWER <i>new</i>	1	19.90	✓ 19.90
REAR BUMPER <i>new</i>	1	617.20	+ 617.20
REAR BUMPER SIDE RETAINER RH <i>new</i>	1	75.40	+ 75.40
REAR RH DOOR <i>Dented</i>	1	922.50	✓ 922.50
REAR RH DOOR CHECKER <i>new</i>	1	49.50	+ 49.50
REAR RH DOOR GLASS REGULATOR MOTOR <i>new</i>	1	285.20	✓ 285.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM CHIN PENG
BLK 419 PASIR RIS DR 6 #08-273
SINGAPORE 510419

Contact : 97825573

TAX INVOICE

Repair Code : CLM18404

Date in : 09/10/2024

Vehicle Num. : SMV2504E

Model : HONDA CIVIC 1.6 VTI CVT

Chassis/Eng# : MRHFC5650LT000290/R16B25520391

REAR RH DOOR HINGE (LOWER) <i>new</i>	1	49.50	+	49.50
REAR RH DOOR HINGE (TOP) <i>new</i>	1	49.50	+	49.50
REAR RH DOOR INNER TRIM BOARD <i>changed</i>	1	465.20	-	465.20
REAR RH DOOR MECHANISM LOCK <i>Replaced</i>	1	231.50	-	231.50
REAR RH DOOR OUTER CHROME MOULDING <i>Replaced</i>	1	75.70	-	75.70
REAR RH DOOR OUTER HANDLE <i>new</i>	1	129.20	+	129.20
REAR RH DOOR WEATHER STRIP <i>for</i>	1	107.20	-	107.20
REAR RH DOOR WEATHER STRIP LOWER <i>new</i>	1	17.40	+	17.40
REAR RH FENDER <i>Dented</i>	1	1353.90		1,353.90
REAR RH FENDER INNER SHIELD COVER <i>new</i>	1	63.40	+	63.40
REAR RH FENDER INNER TRIM BOARD <i>new</i>	1	124.30	+	124.30
REAR RH FENDER WINDSCREEN OUTER CHROME MOULDING <i>new</i>	1	56.50	+	56.50
REAR RH KNUCKLE ARM	1	346.20	+	346.20
REAR RH KNUCKLE ARM BEARING <i>new</i>	1	294.20	+	294.20
REAR RH LOWER ARM <i>new</i>	1	174.20	+	174.20
REAR RH SHOCK ABSORBER	1	255.80	+	255.80
ROCKER GARNISH <i>Replaced</i>	1	242.50	✓	242.50
ROCKER PANEL <i>new</i>	1	608.20	+	608.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM CHIN PENG
BLK 419 PASIR RIS DR 6 #08-273
SINGAPORE 510419

Contact : 97825573

TAX INVOICE

Repair Code : CLM18404
Date in : 09/10/2024
Vehicle Num. : SMV2504E
Model : HONDA CIVIC 1.6 VTI CVT
Chassis/Eng# : MRHFC5650LT000290/R16B25520391

		Subtotal before discount	9,494.80
Percentage discount	20%		1,898.96
		Sub-total 1	7,595.84
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	<i>new</i>	1 50.00	<i>30</i> 50.00
REAR BUMPER CLIPS - SET	<i>new</i>	1 50.00	<i>x</i> 50.00
REAR RH 225/50R17 TYRE	<i>new</i>	1 500.00	<i>+</i> 500.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	<i>new</i>	1 50.00	<i>30</i> 50.00
REAR RH FENDER INNER SHIELD COVER CLIPS - SET	<i>new</i>	1 30.00	<i>x</i> 30.00
REAR RH FENDER INNER TRIM BOARD CLIPS - SET	<i>new</i>	1 50.00	<i>30</i> 50.00
REAR RH FENDER WINDSCREEN SEALANT	<i>new</i>	1 80.00	<i>60</i> 80.00
REAR RH SPORT RIM	<i>new</i>	1 900.00	<i>450</i> 900.00
ROCKER GARNISH CLIPS - SET	<i>new</i>	1 50.00	<i>30</i> 50.00
		Subtotal before discount	1,760.00
Percentage discount	0%		0.00
		Sub-total 2	1,760.00
		Parts-total	9,355.84

LABOUR

to remove, reinstall windscreen (REAR)

120 ~~150.00~~

To remove, reinstall fender glass

40 ~~100.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM CHIN PENG
 BLK 419 PASIR RIS DR 6 #08-273
 SINGAPORE 510419

Contact : 97825573

TAX INVOICE

Repair Code : CLM18404

Date in : 09/10/2024

Vehicle Num. : SMV2504E

Model : HONDA CIVIC 1.6 VTI CVT

Chassis/Eng# : MRHFC5650LT000290/R16B25520391

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

+ 150.00

To road test driving, check and resetting wheel alignments system.

80. 100.00

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

120. 180.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1100. 1,800.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

900. 1,800.00

To apply anti-rust chemical on repaired and replaced panel.

60. 140.00

Labour Total

4,420.00

Parts & Labour Total

13,775.84

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian G
 10/10/24.
 07 days.