

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0755/2024/KS
DATE : 11-Oct-24
WIP : 33886

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MDM TAN SOH LING MRS CHIA CHER KENG @ CHIA CHER KENG
ADDRESS : 1011 UPPER SERANGOON ROAD
#04-03
SINGAPORE 534749
TELEPHONE : HP +65 94870919
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100492074-07
VEHICLE NO : **ES 7017 K**
MODEL CODE : AUDI A1 SB 1.0 TFSI S TRONIC
MODEL YEAR : 28/11/2016
ENGINE NO : CHZ 123184
CHASSIS NO : WAUZZZ8X2HB013753
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8/10/2023
PLACE OF ACCIDENT : 43 NAMLY DR, SINGAPORE 267457

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. ES 707 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$	280.00	
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT.	S/N \$	480.00	
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$	350.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	1,900.00	
6	TO RENEW RHS FRONT RIM WITH TYRE AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	
7	TO REMOVE AND REINSTALL FRONT SUSPENSION . INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N \$	3,200.00	
8	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$ 9,122.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ES 707 K.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,955.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 277.00	
3	FRONT BUMPER HINGE BRACKET - RH	1	\$ 43.00	
4	FRONT BUMPER ADAPTOR - RH	1	\$ 22.00	
5	FRONT BUMPER GRILLE - CENTER	1	\$ 245.00	
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 210.00	
7	FRONT BUMPER AIR GUIDE GRILLE- RH	1	\$ 507.00	
8	HEADLIGHT - RH	1	\$ 2,240.00	
9	HEADLIGHT MOUNTING - RH	1	\$ 147.00	
10	LIFT CYLINDER - RH	1	\$ 170.00	
11	LIFT CYLINDER HOSE	1	\$ 233.00	
12	FRONT FENDER - RH	1	\$ 1,058.00	
13	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 52.00	
14	FRONT FENDER BRACKET - RH FRONT	1	\$ 73.00	
15	FRONT FENDER BRACE - RH FRONT	1	\$ 83.00	
16	FRONT FENDER RIVET - RH	4	\$ 17.00	
17	FRONT FENDER BRACKET - CENTRE RH	1	\$ 70.00	
18	FRONT WHEEL HOUSING LINER - RH	1	\$ 204.00	
19	FRONT WHEEL HOUSING LINER ATTACHMENT - RH	1	\$ 47.00	
20	FRONT ALUMINIUM RIM - RH	1	\$ 1,394.00	
SUB TOTAL SPARE PARTS		:	\$ 9,047.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ES 707 K.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT ALUMINIUM RIM RUBBER VALVE - RH	1	\$ 5.00	
22	FRONT LOWER ARM - RH	1	\$ 394.00	
23	FRONT WHEEL BEARING HOUSING - RH	1	\$ 601.00	
24	FRONT WHEEL HUB - RH	1	\$ 504.00	
25	FRONT LOWER ARM JOINT - RH	1	\$ 135.00	
26	FRONT ANTI-ROLL BAR	1	\$ 276.00	
27	FRONT ANTI-ROLL BAR BUSH	2	\$ 31.00	
28	FRONT COUPLING ROD	2	\$ 216.00	
29	FRONT DRIVESHAFT - RH	1	\$ 2,224.00	
30	FRONT SHOCK ABSORBER	1	\$ 471.00	
31	FRONT ASSEMBLY CARRIER	1	\$ 1,218.00	
32	FRONT ASSEMBLY CARRIER SUPPORT RH	1	\$ 34.00	
33	STEERING GEAR	1	\$ 3,282.00	
34	STEERING GEAR TIE ROD - RH	1	\$ 102.00	
35	STEERING GEAR TIE ROD END - RH	1	\$ 125.00	
36	NOISE INSULATION	1	\$ 367.00	
37	FRONT TYRE - RH	1	TBC	
38	SUNDRIES		\$ 800.00	
TOTAL SPARE PARTS		:	\$ 19,832.00	
TOTAL LABOUR CHARGES		:	\$ 9,122.00	
GRAND TOTAL		:	\$ 28,954.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT