


55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. ES 707 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$	280.00	Xm
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT.	S/N \$	480.00	/
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$	350.00	250
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	1000 /
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	1,900.00	1100 /
6	TO RENEW RHS FRONT RIM WITH TYRE AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	/
7	TO REMOVE AND REINSTALL FRONT SUSPENSION . INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N \$	3,200.00	/
8	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$ 9,122.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ES 707 K.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER repair def	1	\$	1,955.00	1564
2	FRONT BUMPER FIXING PARTS X ^{an}	1	\$	277.00	
3	FRONT BUMPER HINGE BRACKET - RH X ^{an}	1	\$	43.00	
4	FRONT BUMPER ADAPTOR - RH ? s ^{vc}	1	\$	22.00	
5	FRONT BUMPER GRILLE - CENTER X ^{an}	1	\$	245.00	
6	FRONT BUMPER CLOSING ELEMENT ? x ^{su}	1	\$	210.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH M/s ✓	1	\$	507.00	405.60
8	HEADLIGHT - RH s ^{vc} ✓	1	\$	2,240.00	1792.00
9	HEADLIGHT MOUNTING - RH ? x ^{su}	1	\$	147.00	
10	LIFT CYLINDER - RH am ✓	1	\$	170.00	136
11	LIFT CYLINDER HOSE ? x ^{su}	1	\$	233.00	
12	FRONT FENDER - RH repair	1	\$	1,058.00	
13	FRONT FENDER ATTACHMENT PARTS - RH X ^{an}	1	\$	52.00	
14	FRONT FENDER BRACKET - RH FRONT X ^{an}	1	\$	73.00	
15	FRONT FENDER BRACE - RH FRONT X ^{an}	1	\$	83.00	
16	FRONT FENDER RIVET - RH X ^{an}	4	\$	17.00	
17	FRONT FENDER BRACKET - CENTRE RH X ^{an}	1	\$	70.00	
18	FRONT WHEEL HOUSING LINER - RH ? f ^{su}	1	\$	204.00	
19	FRONT WHEEL HOUSING LINER ATTACHMENT - RH X ^{an}	1	\$	47.00	
20	FRONT ALUMINIUM RIM - RH * ? x ^{su}	1	\$	1,394.00	
SUB TOTAL SPARE PARTS		:	\$	9,047.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ES 707 K.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT ALUMINIUM RIM RUBBER VALVE - RH ? Xsue	1	\$	5.00	
22	FRONT LOWER ARM - RH ? bt/	1	\$	394.00	314.80
23	FRONT WHEEL BEARING HOUSING - RH ? bt/	1	\$	601.00	480.40
24	FRONT WHEEL HUB - RH ? bt/	1	\$	504.00	402.80
25	FRONT LOWER ARM JOINT - RH ? bt/	1	\$	135.00	107.60
26	FRONT ANTI-ROLL BAR ? Xsue	1	\$	276.00	
27	FRONT ANTI-ROLL BAR BUSH ? Xsue	2	\$	31.00	
28	FRONT COUPLING ROD ? Xsue	2	\$	216.00	
29	FRONT DRIVESHAFT - RH ? Xsue	1	\$	2,224.00	
30	FRONT SHOCK ABSORBER ? bt/	1	\$	471.00	376.80
31	FRONT ASSEMBLY CARRIER ? Xsue	1	\$	1,218.00	
32	FRONT ASSEMBLY CARRIER SUPPORT RH ? Xsue	1	\$	34.00	
33	STEERING GEAR ? Xsue	1	\$	3,282.00	
34	STEERING GEAR TIE ROD - RH ? bt/	1	\$	102.00	81.60
35	STEERING GEAR TIE ROD END - RH ? bt/	1	\$	125.00	100
36	NOISE INSULATION ? Xsue	1	\$	367.00	
37	FRONT TYRE - RH Xan	1		TBC	
38	SUNDRIES ? nu/		\$	800.00	124.96
TOTAL SPARE PARTS		:	\$	19,832.00	
TOTAL LABOUR CHARGES		:	\$	9,122.00	
GRAND TOTAL		:	\$	28,954.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Rasim - H6 90010068
SURVEYED DATE : 11/10/24
AUTHORISED DATE :
EXCESS COST : 7 days
LIABILITY : EXCESS: TH9
REMARKS : Repair
Res 54 part

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT