

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

Not Authorised

den
means

15/10/24

4 days 1/s \$2800
wh. ph. Atteridge

VEHICLE No: GBH 7749L

1PC	TAILGATE	R	\$2,149.20 X
1PC	TAILGATE REAR LOGO	rec	\$78.00
1PC	TAILLAMP O/S	one	\$386.20
1PC	TAILLAMP PANEL O/S	20/20	\$629.10
1PC	TAILLAMP LOWER GARNISH O/S	20	\$175.20
1PC	TAILLAMP LOWER GARNISH BRACKET O/S	one	\$52.50
1PC	REAR BUMPER	Dis	\$688.60
1PC	REAR BUMPER STEP BRACKET	R	\$155.20
1PC	REAR BUMPER SIDE HOLDER O/S	one	\$105.00
1PC	REAR END PANEL OUTER	R	\$559.70 X
1PC	REAR AIR VENT O/S	1m	\$78.50
1PC	REAR FENDER O/S	R	\$2,049.20 X
			\$7,106.40
		LESS 25%	\$5,329.80

S.NETT

1PC	REAR WINDSCREEN SEALANT	11	\$50.00 X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00 X
1SET	TAILGATE 70Km/h & 8 PAX STICKER KIV	rec	\$20.00 X
1SET	TAILGATE CORPORATE KIV	den	\$850.00 X
1SET	REAR BUMPER CLIPS	den	\$50.00
1SET	REAR BUMPER REVERSE SENSOR	malfunction	\$200.00
1SET	REAR FENDER BODY STICKER KIV	den	\$1,000.00 X
1PC	REAR WHEEL HUB CAP O/S	R	\$150.00 X

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00 40
TO DISMANTLE & REPLACED REAR WINDSCREEN	11 \$120.00 X
TO TRANSFER TAILGATE MECHANISM	11 \$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00 700
TO PUTTY & SPRAY PAINTING	\$1,080.00 850
TOTAL	\$10,129.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

R 2193.1
252
164483
250
1610