

Not Authorized
21/11/2024 \$2650/1

AAD2410-002

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9925G

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9925G

JTDKB3FU003093292

200303878K

TOYOTA

PRIUS GEN 4

29/9/2024

GY4298S/CHINA

30/12/2020

PART	LIST
1 COVER, REAR BUMPER	\$ Bu 612.68 ✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ Bu cam 419.90 cam 2 ✓
1 COVER, REAR BUMPER, LOWER	\$ Bu 27.93 X
1 GUARD, REAR BUMPER, CENTER	\$ CPM 472.19 ✓
1 RETAINER, REAR BUMPER SIDE, LH	\$ Bu 167.48 X
1 RETAINER, REAR BUMPER SIDE, RH	\$ Bu 167.48 X
1 REFLECTOR ASSY, REFLEX, LH	\$ Bu 49.25 X
1 REFLECTOR ASSY, REFLEX, RH	\$ Bu 49.25 X
1 COVER, FLOOR UNDER, NO.1 LH	\$ Bu 220.50 X
1 COVER, FLOOR UNDER, NO.2 RH	\$ Bu 304.92 X
1 COVER, REAR FLOOR CTR	\$ Bu 290.43 X
1 COVER, DECK TRIM, REAR	\$ Bu 159.39 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ Bu 824.46 X
1 SPOILER SUB-ASSY, REAR	\$ Bu 1,986.92 X
1 SEAL, REAR SPOILER	\$ Bu 21.32 X
1 WEATHERSTRIP, BACK DOOR	\$ Bu 469.25 X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ Bu cam 1,156.89 ✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ Bu 68.88 —
1 PLATE, BACK DOOR NAME, NO.1	\$ Bu 68.88 —
1 ORNAMENT SUB-ASSY, BACK DOOR	\$ Bu 90.30 —
TOTAL	\$ 7,628.30
25%	\$ 1,907.08
	\$ 5,721.23

Special Nett

1SET PARKING AID

1SET REAR BUMPER CLIP

\$ Bu/shan 700.00 22000
\$ Bu 95.00 6000

AAD2410-002

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9925G

- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	nn	150.00	X
\$	nn	200.00	X
\$	nn	130.00	X
\$	mc	80.00	305N
\$	mc	80.00	305N
\$	nir	180.00	X
\$	nn	250.00	X
\$	nn	85.00	X
\$	nn	65.00	X

TOTAL \$ 2,015.00

TOTAL PARTS \$ 7,736.23

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 3001

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 180.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ nn 250.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 4401

To reinstall rear bumper parking sensor.

\$ 170.00 501

To Check Electrical Lighting Concerned.

\$ 170.00 151

AAD2410-002

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9925G

TOTAL \$ 5,030.00

Over All Total \$ 12,766.23

(PART-BY-PART) Repair Days

06 DAYS

2 1/2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: