

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0487/2024/KS
DATE : 21-Jun-24
WIP : 20257

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/6/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. LEE XINGYONG
ADDRESS : BLK 330 SERANGOON AVE 3
#09-375
SINGAPORE 550330
TELEPHONE : HP +65 84987291
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220020096-02
VEHICLE NO : **SKB 4006 S**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI
MODEL YEAR : 25/2/2022
ENGINE NO : DEM 035997
CHASSIS NO : WAUZZZF56NA010731
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Jun-24
PLACE OF ACCIDENT : CRAWFORD LANE



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKB 4006 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	1000 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET	\$	2,100.00	1100 ✓
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N \$	480.00	? X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$	6,152.00

Carin 28/6 wip-20257

PREMIUM AUTOMOBILES

Veron



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AZG - Admin

- 4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 4006 S.

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	
					REMARKS
1	FRONT BUMPER <i>beh d</i>	1	\$ 2,802.00	✓	2341.60
2	FRONT BUMPER SECURING STRIP <i>ac u</i>	2	\$ 90.00	+	
3	FRONT BUMPER GRILLE - CENTER <i>neu</i>	1	\$ 245.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	1	\$ 329.00	+	
5	FRONT BUMPER SPOILER <i>neu</i>	1	\$ 675.00	+	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>neu</i>	2	\$ 112.00	+	
7	FRONT BUMPER CLOSING ELEMENT <i>neu</i> <i>Could</i>	1	\$ 329.00	+	262.80
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>neu</i>	2	\$ 338.00	+	
9	FRONT BUMPER TRIM - LH / RH <i>neu</i>	2	\$ 120.00	+	
10	FRONT BUMPER TRIM - CENTER <i>neu</i>	1	\$ 143.00	+	
11	RADIATOR GRILLE <i>Could</i>	1	\$ 2,098.00	✓	1678.40
12	"360" CAMERA <i>neu</i> <i>nn</i>	1	\$ 1,353.00	+	?
13	"360" CAMERA BRACKET <i>neu</i> <i>nn</i>	1	\$ 24.00	+	?
14	"360" CAMERA SECURING PLATE <i>neu</i> <i>nn</i>	1	\$ 18.00	+	?
15	"360" CAMERA CAP <i>neu</i> <i>Missing</i>	1	\$ 158.00	+	126
16	FRONT PARKING AID SENSOR <i>neu</i>	2	\$ 572.00	+	
17	FRONT PARKING AID SENSOR SEAL RING <i>neu</i>	4	\$ 11.00	+	
18	FRONT BUMPER TOP COVER <i>beh d</i>	1	\$ 160.00	?	127.60
19	"CAUTION" SIGN <i>neu</i>	1	\$ 25.00	?	19.44
20	"A/C" STICKER <i>neu</i>	1	\$ 10.00	?	7.52
SUB TOTAL SPARE PARTS			\$ 9,612.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 4006 S.

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LOCK CARRIER BRACKET <i>Asu Dmg</i>	1	\$ 173.00	<i>fls. 138</i>
22	FRONT REINFORCEMENT BEAM <i>New Dented</i>	1	\$ 1,033.00	<i>fls. 836.40</i>
23	FRONT REINFORCEMENT BEAM BRACKET - LH / RH <i>Asu</i>	2	\$ 572.00	<i>146.40</i>
24	FRONT FOAM FILLER PIECE <i>Asu Cracked</i>	1	\$ 183.00	<i>fls. 24</i>
25	OUTSIDE TEMP SENSOR BRACKET <i>fls</i>	1	\$ 30.00	<i>fls.</i>
26	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>Asu Dmg</i>	2	\$ 74.00	<i>57.52</i>
27	LED HEADLIGHT - LH	1	\$ 9,204.00	
28	LED HEADLIGHT SPACER - LH	3	\$ 150.00	
29	LIFT CYLINDER - LH	1	\$ 238.00	
30	LIFT CYLINDER BRACKET - LH	1	\$ 19.00	
31	LIFT CYLINDER HOSE	1	\$ 118.00	
32	BONNET <i>Dented</i>	1	\$ 3,538.00	<i>2830.40</i>
33	BONNET ATTACHMENT PARTS <i>Asu</i>	1	\$ 138.00	
34	BONNET HINGE - LH / RH <i>Asu</i>	2	\$ 1,020.00	
35	BONNET IMPACT PROTECTION - CENTER <i>fls</i>	1	\$ 36.00	<i>38.40</i>
36	BONNET IMPACT PROTECTION - LH / RH <i>fls</i>	2	\$ 72.00	<i>56.24</i>
37	BONNET SOUND ABSORBER	1	\$ 431.00	
38	FRONT FENDER TOP COVER - LH	1	\$ 90.00	
39	FRONT FENDER LEDGE COVER - LONG	1	\$ 45.00	
40	FRONT FENDER LEDGE COVER - SHORT	1	\$ 55.00	
SUB TOTAL SPARE PARTS		:	\$ 16,013.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 4006 S.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET STRIKER - LH / RH <i>new</i>	1	\$ 126.00	+
42	BONNET LID LOCK <i>new</i>	2	\$ 491.00	+
43	BONNET BOWDEN CABLE - CENTER <i>new Dnd</i>	1	\$ 71.00	✓ <i>SS 5640</i>
44	BONNET BOWDEN CABLE COVER - CENTER <i>new</i>	1	\$ 12.00	+
45	BONNET BOWDEN CABLE - CENTER <i>new</i>	1	\$ 71.00	+
46	BONNET LOCK CABLE <i>new</i>	1	\$ 92.00	+
47	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$ 80.00	+
48	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$ 54.00	✓ <i>SS 42.24</i>
49	RADIATOR AIR GUIDE - UPPER <i>new</i>	1	\$ 27.00	+
50	RADIATOR AIR GUIDE - LOWER <i>new</i>	1	\$ 40.00	+
51	SUNDRIES <i>new</i> nec	1	\$ 500.00	✓ <i>3.20</i>
52	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓ <i>60</i>
TOTAL SPARE PARTS			\$ 27,249.00	
TOTAL LABOUR CHARGES			\$ 6,152.00	
GRAND TOTAL			\$ 33,401.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *24/06/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *we Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT