

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0487/2024/KS  
**DATE** : 21-Jun-24  
**WIP** : 20257

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/6/2024**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MR. LEE XINGYONG  
**ADDRESS** : BLK 330 SERANGOON AVE 3  
#09-375  
SINGAPORE 550330  
**TELEPHONE** : HP +65 84987291  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220020096-02  
**VEHICLE NO** : **SKB 4006 S**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFSI  
**MODEL YEAR** : 25/2/2022  
**ENGINE NO** : DEM 035997  
**CHASSIS NO** : WAUZZZF56NA010731  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 21-Jun-24  
**PLACE OF ACCIDENT** : CRAWFORD LANE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKB 4006 S

| S/N                         | NATURE OF JOBS                                                                                                                             |        | ESTIMATED<br>CHARGES       | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID. | S/N \$ | 480.00 ✓                   |                               |
| 2                           | TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.                                                                        | S/N \$ | 400.00 ✗                   |                               |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.       | \$     | <del>2,400.00</del> 1000 ✓ |                               |
| 4                           | TO RESPRAY FRONT BUMPER AND BONNET                                                                                                         | \$     | <del>2,100.00</del> 1100 ✓ |                               |
| 5                           | TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.                                                            | S/N \$ | 480.00 ?                   |                               |
| 6                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                             | S/N \$ | 292.00 ✓                   |                               |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                            | :      | <b>\$ 6,152.00</b>         |                               |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 4006 S.**

|                              |                                                         |     | DAMAGED PARTS & PRICES |         |   |
|------------------------------|---------------------------------------------------------|-----|------------------------|---------|---|
| S/N                          | PARTS DESCRIPTION                                       | QTY | S/NETT                 | REMARKS |   |
| 1                            | FRONT BUMPER <i>Rehd</i>                                | 1   | \$ 2,802.00            | ✓       |   |
| 2                            | FRONT BUMPER SECURING STRIP <i>ne u</i>                 | 2   | \$ 90.00               | +       |   |
| 3                            | FRONT BUMPER GRILLE - CENTER <i>ne u</i>                | 1   | \$ 245.00              | +       |   |
| 4                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>ne u</i> | 1   | \$ 329.00              | +       |   |
| 5                            | FRONT BUMPER SPOILER <i>ne u</i>                        | 1   | \$ 675.00              | +       |   |
| 6                            | FRONT BUMPER AIR GUIDE - LH / RH <i>ne u</i>            | 2   | \$ 112.00              | +       |   |
| 7                            | FRONT BUMPER CLOSING ELEMENT <i>ne u</i>                | 1   | \$ 329.00              | +       |   |
| 8                            | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>ne u</i>     | 2   | \$ 338.00              | +       |   |
| 9                            | FRONT BUMPER TRIM - LH / RH <i>ne u</i>                 | 2   | \$ 120.00              | +       |   |
| 10                           | FRONT BUMPER TRIM - CENTER <i>ne u</i>                  | 1   | \$ 143.00              | +       |   |
| 11                           | RADIATOR GRILLE <i>could</i>                            | 1   | \$ 2,098.00            | ✓       |   |
| 12                           | "360" CAMERA <i>ne u</i>                                | 1   | \$ 1,353.00            | +       | ? |
| 13                           | "360" CAMERA BRACKET <i>ne u</i>                        | 1   | \$ 24.00               | +       | ? |
| 14                           | "360" CAMERA SECURING PLATE <i>ne u</i>                 | 1   | \$ 18.00               | +       | ? |
| 15                           | "360" CAMERA CAP <i>ne u</i>                            | 1   | \$ 158.00              | +       |   |
| 16                           | FRONT PARKING AID SENSOR <i>ne u</i>                    | 2   | \$ 572.00              | +       |   |
| 17                           | FRONT PARKING AID SENSOR SEAL RING <i>ne u</i>          | 4   | \$ 11.00               | +       |   |
| 18                           | FRONT BUMPER TOP COVER <i>?</i>                         | 1   | \$ 160.00              | ?       |   |
| 19                           | "CAUTION" SIGN <i>?</i>                                 | 1   | \$ 25.00               | ?       |   |
| 20                           | "A/C" STICKER <i>?</i>                                  | 1   | \$ 10.00               | ?       |   |
| <b>SUB TOTAL SPARE PARTS</b> |                                                         | :   | <b>\$ 9,612.00</b>     |         |   |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 4006 S.**

|                              |                                                       |     | DAMAGED PARTS & PRICES |         |
|------------------------------|-------------------------------------------------------|-----|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                                     | QTY | S/NETT                 | REMARKS |
| 21                           | LOCK CARRIER BRACKET <i>new</i>                       | 1   | \$ 173.00              | +       |
| 22                           | FRONT REINFORCEMENT BEAM <i>new</i>                   | 1   | \$ 1,033.00            | +       |
| 23                           | FRONT REINFORCEMENT BEAM BRACKET - LH / RH <i>new</i> | 2   | \$ 572.00              | +       |
| 24                           | FRONT FOAM FILLER PIECE <i>new</i>                    | 1   | \$ 183.00              | +       |
| 25                           | OUTSIDE TEMP SENSOR BRACKET <i>new</i>                | 1   | \$ 30.00               | +       |
| 26                           | LOCK CARRIER BRACKET SUPPORT - LH / RH <i>new</i>     | 2   | \$ 74.00               | +       |
| 27                           | LED HEADLIGHT - LH                                    | 1   | \$ 9,204.00            | +       |
| 28                           | LED HEADLIGHT SPACER - LH                             | 3   | \$ 150.00              | +       |
| 29                           | LIFT CYLINDER - LH                                    | 1   | \$ 238.00              | +       |
| 30                           | LIFT CYLINDER BRACKET - LH                            | 1   | \$ 19.00               | +       |
| 31                           | LIFT CYLINDER HOSE                                    | 1   | \$ 118.00              | +       |
| 32                           | BONNET <i>Derided</i>                                 | 1   | \$ 3,538.00            | ✓       |
| 33                           | BONNET ATTACHMENT PARTS <i>new</i>                    | 1   | \$ 138.00              | +       |
| 34                           | BONNET HINGE - LH / RH <i>new</i>                     | 2   | \$ 1,020.00            | +       |
| 35                           | BONNET IMPACT PROTECTION - CENTER <i>new</i>          | 1   | \$ 36.00               | ✓       |
| 36                           | BONNET IMPACT PROTECTION - LH / RH <i>new</i>         | 2   | \$ 72.00               | ✓       |
| 37                           | BONNET SOUND ABSORBER                                 | 1   | \$ 431.00              | +       |
| 38                           | FRONT FENDER TOP COVER - LH <i>new</i>                | 1   | \$ 90.00               | +       |
| 39                           | FRONT FENDER LEDGE COVER - LONG                       | 1   | \$ 45.00               | +       |
| 40                           | FRONT FENDER LEDGE COVER - SHORT                      | 1   | \$ 55.00               | +       |
| <b>SUB TOTAL SPARE PARTS</b> |                                                       | :   | <b>\$ 16,013.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 4006 S.**

|                             |                                               |     | DAMAGED PARTS & PRICES |                  |          |
|-----------------------------|-----------------------------------------------|-----|------------------------|------------------|----------|
| S/N                         | PARTS DESCRIPTION                             | QTY | S/NETT                 | REMARKS          |          |
| 41                          | BONNET STRIKER - LH / RH <i>den</i>           | 1   | \$                     | 126.00           | <i>+</i> |
| 42                          | BONNET LID LOCK <i>den</i>                    | 2   | \$                     | 491.00           | <i>+</i> |
| 43                          | BONNET BOWDEN CABLE - CENTER <i>den</i>       | 1   | \$                     | 71.00            | <i>+</i> |
| 44                          | BONNET BOWDEN CABLE COVER - CENTER <i>den</i> | 1   | \$                     | 12.00            | <i>+</i> |
| 45                          | BONNET BOWDEN CABLE - CENTER <i>den</i>       | 1   | \$                     | 71.00            | <i>+</i> |
| 46                          | BONNET LOCK CABLE <i>den</i>                  | 1   | \$                     | 92.00            | <i>+</i> |
| 47                          | RADIATOR AIR GUIDE - LH / RH                  | 2   | \$                     | 80.00            | <i>+</i> |
| 48                          | RADIATOR AIR GUIDE - LH / RH                  | 2   | \$                     | 54.00            | <i>+</i> |
| 49                          | RADIATOR AIR GUIDE - UPPER                    | 1   | \$                     | 27.00            | <i>+</i> |
| 50                          | RADIATOR AIR GUIDE - LOWER                    | 1   | \$                     | 40.00            | <i>+</i> |
| 51                          | SUNDRIES <i>den</i>                           | 1   | \$                     | 500.00           | <i>+</i> |
| 52                          | FRONT NO PLATE <i>Dented</i>                  | S/N | \$                     | 60.00            | <i>✓</i> |
| <b>TOTAL SPARE PARTS</b>    |                                               | :   | \$                     | <b>27,249.00</b> |          |
| <b>TOTAL LABOUR CHARGES</b> |                                               | :   | \$                     | <b>6,152.00</b>  |          |
| <b>GRAND TOTAL</b>          |                                               | :   | \$                     | <b>33,401.00</b> |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian  
24/06/24

we Authorised 04 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT