

Date: 4/10/2024
Vehicle No: SJV8774M
Model: MERCEDES CLA 180
Chassis: WDD1173422N458530
Reg.Year: 2017

Third Party Insurer: III
Third Party Veh No: SML5596Y
Date of Accident: 3/10/2024
Estimator: JONATHAN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RHF DOOR			\$ 1,300.00
	RHF WINDOW REGULATOR			\$ 420.00
	RHR DOOR			\$ 1,450.00
	RHS ROCKER PANEL			REPAIR
SUB TOTAL				\$ 3,170.00
Cost +10%				\$ 317.00
PARTS TOTAL				\$ 3,487.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS XNN			\$ 50.00
S/N TOTAL				\$ 50.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas	\$	800.00	4001
To perform wiring checks on electrical systems	\$	30.00	201
To remove, putty, repair, sand and respray affected areas	\$	840.00	6601
To remove, replace & refix bumper sensors	\$	30.00	~ X
To remove, replace & reinstall Bootlid inner mechanism	\$	30.00	~ X
To perform Adas Checks, Calibration & Programming	\$	200.00	~ X
Sundries	\$	42.00	~ X

LABOUR TOTAL \$ 1,972.00

JONATHAN	LKK Auto Consultants hence notify the Repairer of the following:	TOTAL	\$	5,509.00
----------	--	-------	----	----------

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No denial of insurance claim is allowed
- Supplementary estimate should be surveyed and is subject to final approval from Insurance Company

Not withstanding
L1Lm & 3200h
Resurvey after 4 days