


SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/10/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SMB1305A
Case Reference Number	BUS/09/24/5077
Registration Date	1/24/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Abdul Rahim Bin Maulod
Type of Accident	Side Swipe
Accident Date and Time	9/30/2024 5:15 PM
Accident Reported Date and Time	10/8/2024 9:50 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1305A - LEFT FRONT BUMPER CRACKED GBL2993L (TP) - 3P insured wit India International Insurance 09.10.2024 (KC) TP INSN NO RESULT. *KAREN PLS UPDATE TP INSURANCE*
Prepared Date and Time	10/10/2024 2:46 PM
Chassis Number	WMAA22ZZ3D7001722
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$2,561.40	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,407.40	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	10/10/2024 2:51 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
10/10/24, 4.30 pm
Without Prejudice
2 days
L/S
Resurvey After Spray

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/10/2024

User ID : choonhwee03

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	795
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	616
Total Spray Painting & Panel Beating	\$786.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009375	VM		RETAINER:MALE & FEMALE,REAR LID,MAN BUS	1.00	\$74.80	10.00	\$67.32	Replace	?
6010153	Body	F01001-CW264	COVER,HEADLAMP:FRT ,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	/ BR
6010304	VE	8-25101-6539	HEADLAMP,LH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	/ BR
6010306	VE	81-25320-6111	FLASHER,AUX HEADLAMP,LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	/ BR
6010073	Body	F01001-CW262	DOVE:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	x Repair
Total					\$6,375.00		\$3,201.75		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									