

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0409/24

DATE : 03-OCT-2024

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : CHONG ZEE LIANG
ADDRESS : 30 BAYSHORE ROAD
#09-06
S(469974)
TELEPHONE NO : 98368916

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SMZ883C
MODEL CODE : FDWARF9E13HDAY646Z
MODEL/YEAR : NISSAN NOTE 1.2L E-POWER PREMIUM (I) MY2020
ENGINE NO : HR12042210L-E13BC
CHASSIS NO : JN1FAAE13Z0900958
MILEAGE : 70393 KM
DATE IN : 03/10/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 02/10/2024

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
her
means
21/10/24
wh plus before party
4 days.
P/P to 4057.34

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMZ883C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR REAR PANEL, RENEW REAR BUMPER AND TAIL GATE BACK DOOR. 430	1200.00	645 -
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME. 380	1300.00	700 -
3	ZZ/003	REMOVE AND REVERSE SENSOR AND RESET.	110.00	✓ -
4	ZZ/004	REMOVE AND INSTALL REAR W/SCREEN GLASS.	180.00	✓ -
5	ZZ/005	REMOVE AND INSTALL TAIL GATE BACK DOOR MECHANISM.	80.00	✓ -
6	ZZ/006	APPLY SEALANT TO TAIL GATE BACK DOOR.	100.00	✓ -
7	ZZ/007	SUPPLY REAR LICENSE PLATE.		
8	ZZ/008	CHECK LIGHT SYSTEM.	48.00	✓ -
TOTAL LABOUR CHARGES			3018.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMZ883C

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
1	SUNDRIES	NPN		11	50.00 X
2	REAR LICENCE PLATE	RLP		50	60.00 /
3	REVERSE SENSOR BRACKET CORNER LH	28533-6XJ5E		11	41.90 ✓
4	REVERSE SENSOR BRACKET CENTRE @ \$41.90 EACH	28533-6RB0A		11	83.80 /
5	EMBLEM REAR E-POWER	90893-6XJ0A	11	36.40 /	
6	REAR EMBLEM NOTE	90892-6XJ0A	11	88.80 /	
7	TAIL GATE BACK DOOR LOCK	90502-6XJ0A	11	142.80 X	
8	STRIKER-TAIL GATE	90570-6RA0A	11	38.70 X	
9	BACK DOOR W/STRIP	90830-6XJ0B	11	106.30 X	
10	REAR W/SCREEN SEALANT	SEALANT - 4		11	80.00 /
11	REAR W/SCREEN FASTENER	G2G16-89900	11	71.00 /	
12	REAR W/SCREEN MOULDING	G2891-89925	11	251.90 /	
13	TAIL GATE BACK DOOR	K010M-6XJMA	11	1352.80 /	
14	ENERGY ABSORBER REAR BUMPER	85090-6XJ0A	11	153.60 X	
15	REAR BUMPER TOW HOOK COVER	85071-6XJ0A	11	31.40 X	
16	REAR BUMPER FASCIA LH	85017-6XJ0H	11	196.90 X	
17	REAR BUMPER STAY @ \$108.00 EACH	H5212-1HMMA	11	216.00 X	
18	REAR BUMPER SIDE BRKT LH	85221-6XJ0A	11	19.80 X	
19	CLIP REAR BUMPER @ \$1.50 EACH	01553-10501	11	30.00 /	
20	REAR BUMPER FASCIA	85022-6XJ5A	11	579.90 /	
SUB TOTAL			3316.30	0.00	315.70
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			663.26	0.00	0.00
GRAND TOTAL			2653.04	0.00	315.70
OVERALL TOTAL			2968.74		

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMZ883C

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER		
			NETT	LIST
				S/NETT REMAR

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMZ883C

TOTAL LABOUR CHARGES	3018.00
TOTAL SPARE PARTS CHARGES	2968.74

GRAND TOTAL	5986.74 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.