

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0409/24  
DATE : 03-OCT-2024

INDIA INT'L INSURANCE PTE LTD  
64 CECIL STREET  
#04-05 IOB BUILDING  
S(049711)  
TEL : 63476100  
FAX : 62244174  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : CHONG ZEE LIANG  
ADDRESS : 30 BAYSHORE ROAD  
#09-06  
S(469974)  
TELEPHONE NO : 98368916

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : \*  
VEHICLE NO : SMZ883C  
MODEL CODE : FDWARF9E13HDAY646Z  
MODEL/YEAR : NISSAN NOTE 1.2L E-POWER PREMIUM (I) MY2020  
ENGINE NO : HR12042210L-E13BC  
CHASSIS NO : JN1FAAE13Z0900958  
MILEAGE : 70393 KM  
DATE IN : 03/10/2024  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HAMZAH  
ACCIDENT DATE : 02/10/2024

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMZ883C

| S/NO | JOB CODE | NATURE OF JOB                                                                      | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|------|----------|------------------------------------------------------------------------------------|----------------------|------------------------------|
| 1    | ZZ/001   | LABOUR CHARGES TO REPAIR REAR PANEL, RENEW REAR<br>BUMPER AND TAIL GATE BACK DOOR. | 1200.00              |                              |
| 2    | ZZ/002   | CHARGES TO SPRAY PAINTING SAME.                                                    | 1300.00              |                              |
| 3    | ZZ/003   | REMOVE AND REVERSE SENSOR AND RESET.                                               | 110.00               |                              |
| 4    | ZZ/004   | REMOVE AND INSTALL REAR W/SCREEN GLASS.                                            | 180.00               |                              |
| 5    | ZZ/005   | REMOVE AND INSTALL TAIL GATE BACK DOOR MECHANISM.                                  | 80.00                |                              |
| 6    | ZZ/006   | APPLY SEALANT TO TAIL GATE BACK DOOR.                                              | 100.00               |                              |
| 7    | ZZ/007   | SUPPLY REAR LICENSE PLATE.                                                         |                      |                              |
| 8    | ZZ/008   | CHECK LIGHT SYSTEM.                                                                | 48.00                |                              |
|      |          | TOTAL LABOUR CHARGES                                                               | 3018.00              |                              |

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMZ883C

|                                                       |                                              | DAMAGED PARTS & PRICES |         |      |              |
|-------------------------------------------------------|----------------------------------------------|------------------------|---------|------|--------------|
| S/NO                                                  | PARTS DESCRIPTION                            | PARTS NUMBER           | NETT    | LIST | S/NETT REMAR |
| 1                                                     | SUNDRIES                                     | NPN                    |         |      | 50.00        |
| 2                                                     | REAR LICENCE PLATE                           | RLP                    |         |      | 60.00        |
| 3                                                     | REVERSE SENSOR BRACKET CORNER LH             | 28533-6XJ5E            |         |      | 41.90        |
| 4                                                     | REVERSE SENSOR BRACKET CENTRE @ \$41.90 EACH | 28533-6RB0A            |         |      | 83.80        |
| 5                                                     | EMBLEM REAR E-POWER                          | 90893-6XJ0A            | 36.40   |      |              |
| 6                                                     | REAR EMBLEM NOTE                             | 90892-6XJ0A            | 88.80   |      |              |
| 7                                                     | TAIL GATE BACK DOOR LOCK                     | 90502-6XJ0A            | 142.80  |      |              |
| 8                                                     | STRIKER-TAIL GATE                            | 90570-6RA0A            | 38.70   |      |              |
| 9                                                     | BACK DOOR W/STRIP                            | 90830-6XJ0B            | 106.30  |      |              |
| 10                                                    | REAR W/SCREEN SEALANT                        | SEALANT - 4            |         |      | 80.00        |
| 11                                                    | REAR W/SCREEN FASTENER                       | G2G16-89900            | 71.00   |      |              |
| 12                                                    | REAR W/SCREEN MOULDING                       | G2891-89925            | 251.90  |      |              |
| 13                                                    | TAIL GATE BACK DOOR                          | K010M-6XJMA            | 1352.80 |      |              |
| 14                                                    | ENERGY ABSORBER REAR BUMPER                  | 85090-6XJ0A            | 153.60  |      |              |
| 15                                                    | REAR BUMPER TOW HOOK COVER                   | 85071-6XJ0A            | 31.40   |      |              |
| 16                                                    | REAR BUMPER FASCIA LH                        | 85017-6XJ0H            | 196.90  |      |              |
| 17                                                    | REAR BUMPER STAY @ \$108.00 EACH             | H5212-1HMMMA           | 216.00  |      |              |
| 18                                                    | REAR BUMPER SIDE BRKT LH                     | 85221-6XJ0A            | 19.80   |      |              |
| 19                                                    | CLIP REAR BUMPER @ \$1.50 EACH               | 01553-10501            | 30.00   |      |              |
| 20                                                    | REAR BUMPER FASCIA                           | 85022-6XJ5A            | 579.90  |      |              |
| SUB TOTAL                                             |                                              |                        | 3316.30 | 0.00 | 315.70       |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                                              |                        | 663.26  | 0.00 | 0.00         |
| GRAND TOTAL                                           |                                              |                        | 2653.04 | 0.00 | 315.70       |
| OVERALL TOTAL                                         |                                              |                        | 2968.74 |      |              |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMZ883C

|      |                   | DAMAGED PARTS & PRICES |      |                   |
|------|-------------------|------------------------|------|-------------------|
| S/NO | PARTS DESCRIPTION | PARTS NUMBER           | NETT | LIST S/NETT REMAR |

LEGEND: REMARKS ( OK ) = APPROVED, REMARKS ( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMZ883C

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 3018.00   |
| TOTAL SPARE PARTS CHARGES | 2968.74   |
| -----                     |           |
| GRAND TOTAL               | 5986.74 * |
| -----                     |           |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |   |      |
|-----------------|---|------|
| NAME            | : |      |
| SURVEYED DATE   | : |      |
| AUTHORIZED DATE | : |      |
| EXCESS CLAUSE   | : | 0.00 |
| LIABILITY       | : | 0.00 |
| REMARKS         | : |      |

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.