

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

Reg. No: 20158764H

Email: CA3SERVICES@GMAIL.COM

| | |
|-------------------------------|-------------------------|
| ATTENTION: | MOTOR CLAIMS DEPARTMENT |
| DATE: | 10-10-24 |
| CLAIM TYPE: | T/P CLAIM |
| TO: | AIG |
| VEHICLE DETAILS | |
| VEHICLE NO: | SKS8913H |
| MAKE & MODEL: | BMW 420I |
| CHASSIS NO: | |
| ACCIDENT DETAILS | |
| DATE: | 10 October, 2024 |
| TIME: | 0920HRS |
| THIRD PARTY REQUESTOR: | JACK LI |

CLAIM DETAILS: PARTS

| S/N: | DESCRIPTION | QTY: | UNIT LIST PRICE | TOTAL LIST PRICE |
|------|---|------|-----------------|----------------------------|
| 1 | REAR BUMPER <i>Dehd</i> | 1 | \$ 1,955.30 | \$ 1,955.30 ✓ |
| 2 | REAR BUMPER SIDE RETAINER <i>new</i> | 2 | \$ 150.00 | \$ 300.00 ✗ |
| 3 | REAR BUMPER CENTRE OUTER GARNISH <i>lit</i> | 1 | \$ 520.00 | \$ 520.00 195 ✗ |
| 4 | REAR BUMPER SENSOR <i>new</i> | 2 | \$ 280.00 | \$ 560.00 ✗ |
| 5 | REAR BUMPER TOWING COVER <i>new</i> | 1 | \$ 80.00 | \$ 80.00 ✗ |
| 6 | REAR BUMPER CENTRE GARNISH <i>lit</i> | 1 | \$ 250.00 | \$ 250.00 ✓ |
| 7 | REAR BUMPER REINFORCEMENT <i>Dented</i> | 1 | \$ 850.00 | \$ 850.00 ✓ |

TOTAL PRICE \$ 4,515.30

LESS 5% \$ 225.77

SUB TOTAL PRICE \$ 4,289.54

SPECIAL NETT ITEMS

| S/N: | DESCRIPTION | QTY: | UNIT LIST PRICE | TOTAL LIST PRICE |
|--------------|----------------------------------|------|-----------------|-------------------|
| 1 | REAR BUMPER CLIPS SET <i>new</i> | 1 | \$ 20.00 | \$ 20.00 ✓ |
| TOTAL | | | | \$ 20.00 ✓ |

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

| | | | | |
|---|--|---|-------------|------------------------------|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | 1 | \$ 1,000.00 | \$ 1,000.00 200 ✗ |
| 2 | TO SPRAY PAINT AFFECTED AREA | 1 | \$ 1,000.00 | \$ 1,000.00 200 ✗ |
| 3 | TUFF COAT | 1 | \$ 200.00 | \$ 200.00 ✗ |

| | | | | | |
|---|--|---|-----------|-----------|----|
| 4 | WIRING CHECK | 1 | \$ 80.00 | \$ 80.00 | * |
| 5 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | 1 | \$ 100.00 | \$ 100.00 | SO |

TOTAL \$ 2,380.00 *450*

ESTIMATE REPORT

| | | |
|-------------------|----|----------|
| TOTAL PARTS COST | \$ | 4,309.54 |
| TOTAL LABOUR COST | \$ | 2,380.00 |
| TOTAL REPAIR COST | \$ | 6,689.54 |

APPROVED DETAILS:

SURVEYOR:
 CONTACT NO.:
 PART BY PART/LUMP SUM
 NO. OF DAYS

Admin LG
1/S 14/10/24
02 Days

3687.79
- 20.00
- 450.00

3217.79
211.558

- 20%
2574.232

Lump Sum 22900 & 20A/S