

16 Oct 2024

TP Sampo
Veron

SLM 5920 B VOLVO XC60

No	Qty	Parts Description	Estimated Parts Price
1	1	Tailgate rear XC60 <i>2 new part</i>	\$ 3,042.90 +
2	1	Windscreen rear XC60 <i>new</i>	\$ 1,403.40 +
3	1	"D" primer glass & P	\$ 48.20 +
4	1	"D" glass cleaner H <i>Not new</i>	\$ 102.50 +
5	2	*D* windscreen seala	\$ 340.60 +
6	1	Emblem 'VOLVO' rear	\$ 135.90 ✓
7	1	Emblem 'XC60' CH 365 <i>new</i>	\$ 135.90 ✓
8	1	Emblem 'T5' D.E SPA <i>new</i>	\$ 114.60 ✓
9	1	Bumper cover rear XC <i>Defend</i>	\$ 2,134.10 ✓
10	1	Bumper spoiler rear <i>Defend</i>	\$ 553.30 ✓
11	1	Bumper moulding rear <i>new</i>	\$ 268.70 ✓
12	1	Bumper bracket rear <i>new</i>	\$ 57.40 +
13	1	Protecting plate mat <i>new</i>	\$ 936.60 +
14	1	Tail pipe bracket LH <i>cracked</i>	\$ 51.20 ✓
15	1	Tail pipe bracket RH <i>cracked</i>	\$ 51.20 ✓
16	1	Skid plate rim LH XC <i>both new</i>	\$ 268.70 +
17	1	Skid plate rim RH XC <i>new</i>	\$ 268.70 +
18	1	Bumper bracket LHR X <i>new</i>	\$ 183.90 +
19	1	Bumper bracket RHR X	\$ 183.90 +
20	1	Bumper bracket rear <i>new</i>	\$ 26.90 ✓
21	1	Bumper bracket rear <i>new</i>	\$ 26.90 ✓
22	1	Spoiler bracket rear <i>new</i>	\$ 36.60 ✓
23	1	Heat shield rear XC6	\$ 632.50 +
24	1	Cable harness <i>new</i>	\$ 201.20 +
25	2	Park sensor 29dB 90 <i>1 piece dented</i>	\$ 543.80 <i>271.90</i>
26	1	Bumper rail rear XC6 <i>Dented</i>	\$ 1,613.00 ✓
27	1	Silencer rear XC60	\$ 1,207.40 +
28	1	Exhaust clamp 60mm x	\$ 190.00 ✓
29	1	Exhaust pipe LH <i>new</i>	\$ 220.40 ✓
30	1	Exhaust pipe RH <i>new</i>	\$ 220.40 ✓
31	1	Boot moulding chrome	\$ 305.70 ✓
32	1	Bumper installing MT	\$ 101.40 +
33	10	Bumper clip XC90 16- <i>new</i>	\$ 77.00 +
34	10	Blind rivet 4.0*21 P <i>new</i>	\$ 55.00 +
35	10	Bumper clip 8x8,5 <i>new</i>	\$ 62.00 ✓
36	10	Bumper clip green S6 <i>new</i>	\$ 52.00 +
37	10	Expanding nut XC40 <i>new</i>	\$ 79.00 +
			<u>\$ 15,932.90</u>

Total parts :

\$ 15,932.90

No	Description	Labour Charges
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 120.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 180.00 x
3	To remove and refit rear reverse sensor.	\$ 150.00 50
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00 x
5	To remove and refit rear windscreen glass.	\$ 180.00 x
6	To remove, refit and replace exhaust silencer and mountings.	\$ 200.00 x
7	To apply undercoating on repaired and replaced panel.	\$ 200.00 x
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 2,500.00 400
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 2,400.00 500

Total labour :

\$ 6,010.00

Total parts :

\$ 15,932.90

Total labour :

\$ 6,010.00

Total repair cost :

\$ 21,942.90

total 6288.09

L/S: 5K

03 Days

5k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: