

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24100205/KNP3M4**Date:** 23/10/2024**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372_03
Claimant Vehicle No :	SLF9382P	Insured Vehicle No :	SHD2079U
Date of Loss:	05/10/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF9382P		
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT AWD S/R FACELIFT (A)	Engine No:	4B12RR3686
Reg. Date:	16/09/2016 (Man. Year: 2016)	Chassis No:	JMYXTGF3WGW004231
Colour:	Metallic Grey	Odometer:	164170 km
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,423.30	1,924.80	8,498.50	81.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	820.00	1,200.00	59.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,443.30	2,744.80	9,698.50	77.94
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	12,443.30	2,200.00	10,243.30	82.32
+ GST 9.00/9.00% (S\$)	1,119.90	198.00	921.90	82.32
Nett Amount (S\$)	13,563.20	2,398.00	11,165.20	82.32

INSPECTION

Date of Assignment:	10/10/2024	EM SOLUTION PTE LTD (160 SIN MING) (HQ)
Date Inspected:	14/10/2024	Inspected At: 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2024)
Parts:	M1-SUV	mitsubishi outlander 2.4 cvt awd s/r facelift (a) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF9382P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	935.00 FL	*863.00 FL
2	1		*FRONT BUMPER CTR PAD	Dented	486.00 FL	*321.00 FL
3	1		*FRONT BUMPER LOWER GUARD	Serviceable	526.00 FL	*- FL
4	1		*FRONT BUMPER CHROME MOULDING - RH - TOP	Dented	132.00 FL	*132.00 FL
5	1		*FRONT BUMPER CHROME MOULDING - RH - CTR	Cracked	295.00 FL	*295.00 FL
6	1		*FRONT BUMPER CHROME MOULDING - RH - LOWER	Serviceable	262.00 FL	*- FL
7	1		*FRONT BUMPER SPRAY NOZZLE COVER	Missing	68.00 FL	*68.00 FL
8	1		*FRONT BUMPER FOG LAMP - RH	Serviceable	385.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP COVER	Missing	136.00 FL	*136.00 FL
10	1		*FRONT BUMPER FOG LAMP MOULDING	Serviceable	126.00 FL	*- FL
11	1		*FRONT BUMPER SIDE PROTECTOR - RH	Distorted	192.00 FL	*192.00 FL
12	1		*FRONT BUMPER SIDE RETAINERS - L/R 2PCS	Distorted (1Pc Only)	130.00 FL	*65.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Repair	655.00 FL	*- FL
14	1		*FRONT FENDER - RH	Repair	735.00 FL	*- FL
15	1		*FRONT FENDER PROTECTOR	Serviceable	392.00 FL	*- FL
16	1		*FRONT FENDER INNER SHIELD	Serviceable	189.00 FL	*- FL
17	1		*FRONT HEADLAMP - RH	Serviceable	2,550.00 FL	*- FL
18	1		*FRONT SPORT WHEEL - RH	Serviceable	835.00 FL	*- FL
19	1		*FRONT SHOCK ABSORBER - RH	Serviceable	486.00 FL	*- FL
20	1		*FRONT LOWER ARM	Serviceable	495.00 FL	*- FL
21	1		*FRONT KNUCKLE ARM	Serviceable	510.00 FL	*- FL
22	1		*FRONT WHEEL HUB BEARING	Not Necessary	425.00 FL	*- FL
23	1		*WIPER TANK	Serviceable	192.00 FL	*- FL
24	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
25	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
26	1		*FRONT TYRE - RH	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,537.00	2,132.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,113.70	207.20
Total Parts (\$\$)	10,423.30	1,924.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO CHECK WHEEL ALIGNMENT	New	120.00	0.00
3	TO REMOVE, REFIX FRONT UNDERCARRIAGE	New	250.00	0.00
4	TO RESPRAY PAINTING AND ETC	New	800.00	400.00
5	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	800.00	400.00
Gross Labour Cost (\$\$)			2,020.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >