



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SINGAPORE PRISON SERVICE
LOGISTICS BRANCH SINGAPORE

Ref: CS/SPS24100206/Rnp3e2

Date: 10/10/2024

Code: SPS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 9239P	Veh. Inspected	SLR 324D
Policy No.	-	Coverage	0
Claim No.	6000187434	Excess	\$0.00
Assign From	MUHAMMAD FARIZ ZAKARIA	Assign Date	09/10/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE HYBRID 1.5 A	C.C	1496
Engine No.	LEB4266447	Year of Reg.	28/07/2017
Chassis No.	GP71046171	Colour	GREY
Odometer	517342 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60 R15	RYDANZ	6
L/H Front Tyre	185/60 R15	RYDANZ	6
R/H Rear Tyre	185/60 R15	RYDANZ	6
L/H Rear Tyre	185/60 R15	RYDANZ	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/10/2024	Inspection Date	11/10/2024
Survey held at	LION CITY RENTALS PTE LTD - NO. 4 JALAN BESUT S(619557)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days