LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: LONPAC INSURANCE BHD From: LKK Auto Consultants Pte Ltd

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: GERALD POH Date: 25/07/2024

PRELIMINARY ADVICE

Vehicle NoSMZ 288XAccident Date24/06/2024MakeTOYOTA HARRIER G GRADEPolicy No.Z24VC05022989

Assignment Date 24/06/2024 Excess Inspection Date 26/06/2024 Est. Duration of Repair 3

Inspected At:

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$ 1,920.00
Revised Estimate Amount:	\$ 1,187.50
"Check" Items Amount	\$0.00
Total	\$ 1,187.50

Total Loss Consideration

Book Value	\$0.00
Market Value	\$108,000.00
COE / PARF Rebate	\$44,596.00
Salvage Value	\$0.00
Margin for Repair	\$63,404.00

Remarks

]	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.	
	Kindly let us have your authorisation.	

[] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

[] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.