

No f Accident
26/6/24
3 days
take photo. 100% 4-
2/5 \$ 950

REPAIR ESTIMATE

Claim Type: Third Party Claim Date : 24 Jun 2024
 Attn: Lonpac Insurance Bhd Vehicle Num : SMZ288X
 Motor Claims Department Make/Model : TOYOTA HARRIER G GRADE
 Owner: LAI CHIN MENG Chassis # : JTEKB3GH40J003943
 DOA: 24 Jun 2024 Engine # : 8ARZ146073
 Yr. Of Manu : 2018


No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	ROOF SIDE PANEL RH	1	S\$ 1850.00	S\$ 1850.00 X
2	ROOF SIDE PANEL BLACK MOULDING RH	1	S\$ 290.00	S\$ 290.00 ✓
3	FRONT DOOR WINDSOR VISOR	1	S\$ 280.00	S\$ 280.00 X
				Amt S\$ 1,850.00
DISCOUNT:				25% S\$ 462.50
Subtotal S\$				1,387.50

No.	Description	Qty	U/P	Amt
Section: LABOUR				
4	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		S\$	750.00 300
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		S\$	800.00 550
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION-SEAT, TRIM GARNISH, TRIM LINER CARPET.		S\$	120.00 X
7	REMOVE AND REINSTALL FRONT WINDSCREEN GLASS TO ASSIST REPAIR		S\$	250.00 120
Amt S\$				1920.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LIST ITEMS Subtotal: S\$ 1,387.50
 LABOUR Subtotal: S\$ 1,920.00
 Total: S\$ 3,307.50

290
252
217.50
970
1187.5
950