



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS3/SPF24100207/Kvp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	17/12/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	QX 2714H	Veh. Inspected	PC 9779Y
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/052 (LK)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	26/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ VIANO CDI2.2 (A)	C.C	2143
Engine No.	65194031690254	Year of Reg.	30/08/2013
Chassis No.	WDF63981523819832	Colour	BLACK
Odometer	484982 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55ZR17	KAPSEN	5
L/H Front Tyre	235/55ZR17	KAPSEN	5
R/H Rear Tyre	235/55ZR17	KAPSEN	7
L/H Rear Tyre	235/55ZR17	KAPSEN	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S SLIDING DOOR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/08/2024	Inspection Date	03/10/2024 (11:30)
Survey held at	BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-341 - REPAIRER: JD MOTORSPORTS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days