

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

meraj
15/10/24

15 October 2024

REG NO. : SMA1458Y
MAKE/MODEL : HONDA VEZEL

2/5 @ 3200/
Weight. 11kg x 2

4 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front RH Headlamp	1789.20 \$ scrap 2,418.82 ✓
1	Front Bumper	764.80 \$ cur/To. 1,126.84 ✓
1	Front Bumper Inner Sponge	\$ N S 241.10 X
1	Front Bumper Reinforcement	\$ 1 698.20 X
1	Front Bumper Lower Lid	\$ 1 588.80 X
1	Front Bumper Side Retainer	\$ 1 128.00 X
1	Front RH Fender	450.00 \$ 20/30 568.00 ✓
1	Front RH Fender Inner Shield	266.20 \$ 70 368.60 ✓
1	Front RH Fender Wheel Arch Garnish	280.40 \$ cur/To. 369.50 ✓
1	Front RH Wheel Rim	\$ R 1,260.00 X
1	Front Wheel Hub With Bearing	\$ 1 585.80 X
1	Front Shock Absorber	\$ 1 518.98 X
1	Front Lower Arm	\$ 1 628.00 X
1	Front Knuckle Arm	\$ 1 608.26 X
1	Front Door (RH)	\$ R 3,126.00 X
1	Front Door Checker	\$ 1 155.00 X
1	Front Door Hinges	\$ 1 330.00 X
1	Front Door Inner Board	\$ 1 1,000.00 X
1	Front Door Lock	\$ 1 435.00 X
1	Front Door Protector	\$ 1 225.00 X
1	Front Door Side Mirror	\$ 1 758.00 X
1	Front Door Weatherstrip	\$ 1 295.00 X
1	Rocker Panel	\$ 1 995.00 X
1	Rocker Panel Outer Garnish	\$ 1 655.00 X
		\$ 18,082.90
	Less 20%	\$ 3,616.58
		\$ 14,466.32
<u>SPECIAL NETT ITEMS</u>		
1	Front Tyre	\$ 1 450.00 X
1	Front Fender Inner Shield Clip (1 Set)	\$ 1 80.00 30
1	Front Bumper Clip (1 Set)	\$ 1 90.00 30
		\$ 620.00
<u>LABOUR CHARGES</u>		
1	To Check Wiring, Lighting And Resetting Headlamps Focusing	\$ 80.00 20
2	To Remove And Refit Inner Garnishes	\$ 1 150.00 X
3	To Remove And Refit Front Undercarriage.	\$ 1 350.00 X
4	To Remove, Refit Door Fittings And Replaced Damaged Parts	\$ 1 200.00 X
5	To Conduct Wheel Alignment	\$ 1 180.00 X

6	To Apply Undercoating.	\$	180.00	30
7	Panel Beating.	\$	2,000.00	380
8	To Re-spray Painting On The Affected Areas.	\$	1,800.00	700
		\$	4,940.00	

GRAND TOTAL :

\$ 20,026.32

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 3521.4
202
2817.12
60
1130
4007.12
202
3205