

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC24100208/Uvh3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMA 14584

at Workshop m/s

Wll Garage

of

Insured:

5922181P

Policy No.

Claims No.

MT/1298863-002


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value:

613K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

407f

Date:

Person Contacted:

Vehicle: IN / OUT

21/10/24 8:52

Veh No:

SMA 14584

Yr Regn:

23/06/15Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda veez / 1.5x c.c 1496

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

220912

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU11022165Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

04/10/24

D.O.I.

15/10/24

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 13h.

21/10/24 1/5 83200 inbound Lawrence (red 16,826.32, 84%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

) S + RS SI

: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	407F
Vehicle Details	
Vehicle No.:	SMA1458Y
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2024
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X AUTO
Primary Colour:	Silver
Secondary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B3522180
Chassis No.:	RU11022165
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,014.00
Original Registration Date:	23 Jun 2015
First Registration Date:	23 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$8,014.00 4007
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2025
PARF Rebate Amount:	\$4,007.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$4,185.00
Total Rebate Amount:	\$8,192.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 15 Oct 2024

OK

[New](#) [Used](#) [Electric](#) [Loan](#) [Rent](#) [Sell](#) [Directory](#) [e-Shop](#) [Insurance](#) [Articles](#) [Forum](#)

All Category



Filter

Search

Save Search



2015 X

41 Vehicles

Car Make

Car Model

Price Range

Depreciation

2015

M



PREMIUM AD

Honda Vezel 1.5A X

Honda Sensing

\$16,500

Instl. \$1,468

/mth

\$16,550 /yr

15-Jul-2015
(8mths COE left)

140,000 km

1,496 cc 1 Owner

New arrival. Short term unit for further COE renewal at low cost. Best choice to save more than \$10k for early COE renewal plan. Call now for viewing arrangement to understand more.

Posted 15-Oct-2024

☐ Compare

Honda Vezel 1.5A X

Honda Sensing

\$18,700

Instl. \$1,217

/mth


\$12,910 /yr

06-Nov-2015
(1yr COE left)

98,000 km

1,496 cc 2 Owners

Posted 14-Oct-2024

☐ CompareHonda Vezel
1.5A X

\$19,800

Instl. \$1,095

/mth

\$12,530 /yr

30-Dec-2015
(1yr 2mths COE left)

74,000 km

1,496 cc 1 Owner

1 non PHV owner, super low mileage, low maintenance, bank and inhouse loan are available, no repairs needed, free 1 year warranty plus 2 times car servicing for an added peace of mind, 100% accident free, view to believe it, call now before it is gone

Warranty

SG Car Choice Pte Ltd|Posted 13-Oct-2024

☐ Compare[Compare](#)

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

Meraj
15/10/24

15 October 2024

REG NO. : SMA1458Y
MAKE/MODEL : HONDA VEZEL

d/s 3200
Whipst. Alignment

4 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front RH Headlamp	1789.20 \$ scrap 2,418.82 ✓
1	Front Bumper	764.80 \$ cur/To. 1,126.84 ✓
1	Front Bumper Inner Sponge	\$ NS 241.10 X
1	Front Bumper Reinforcement	\$ 1 698.20 X
1	Front Bumper Lower Lid	\$ 1 588.80 X
1	Front Bumper Side Retainer	\$ 1 128.00 X
1	Front RH Fender	450.80 \$ 2D/34t 568.00 ✓
1	Front RH Fender Inner Shield	266.20 \$ 1 368.60 ✓
1	Front RH Fender Wheel Arch Garnish	280.40 \$ cur/To. 369.50 ✓
1	Front RH Wheel Rim	\$ R 1,260.00 X
1	Front Wheel Hub With Bearing	\$ 1 585.80 X
1	Front Shock Absorber	\$ 1 518.98 X
1	Front Lower Arm	\$ 1 628.00 X
1	Front Knuckle Arm	\$ 1 608.26 X
1	Front Door (RH)	\$ R 3,126.00 X
1	Front Door Checker	\$ 1 155.00 X
1	Front Door Hinges	\$ 1 330.00 X
1	Front Door Inner Board	\$ 1 1,000.00 X
1	Front Door Lock	\$ 1 435.00 X
1	Front Door Protector	\$ 1 225.00 X
1	Front Door Side Mirror	\$ 1 758.00 X
1	Front Door Weatherstrip	\$ 1 295.00 X
1	Rocker Panel	\$ 1 995.00 X
1	Rocker Panel Outer Garnish	\$ 1 655.00 X
		\$ 18,082.90
	Less 20%	\$ 3,616.58
		\$ 14,466.32
<u>SPECIAL NETT ITEMS</u>		
1	Front Tyre	\$ 1 450.00 X
1	Front Fender Inner Shield Clip (1 Set)	\$ 1 80.00 30
1	Front Bumper Clip (1 Set)	\$ 1 90.00 30
		\$ 620.00
<u>LABOUR CHARGES</u>		
1	To Check Wiring, Lighting And Resetting Headlamps Focusing	\$ 80.00 20
2	To Remove And Refit Inner Garnishes	\$ 1 150.00 X
3	To Remove And Refit Front Undercarriage.	\$ 1 350.00 X
4	To Remove, Refit Door Fittings And Replaced Damaged Parts	\$ 1 200.00 X
5	To Conduct Wheel Alignment	\$ 1 180.00 X

6	To Apply Undercoating.	\$	180.00	30
7	Panel Beating.	\$	2,000.00	380
8	To Re-spray Painting On The Affected Areas.	\$	1,800.00	700
		\$	4,940.00	

GRAND TOTAL :

\$ 20,026.32

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged parts, for resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

P. 3521.4
202
2817.12
60
1130
4007.12
202
3205