

EURO SUCCESS SERV PTE. LTD  
1 KAKIT BUKIT AVE 6, #02-03 SINGAPORE 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (Ah Huat)

Vehicle No: SMA 8871R

Model: HYUNDAI ELANTRA

Not Authorized  
11/10/2014  
4 days  
H/s + 3600  
Ah Huat

| QTY      | LIST ITEMS                                       | AMOUNT                    |
|----------|--------------------------------------------------|---------------------------|
| 1        | REAR BUMPER <i>70cm</i>                          | 484.20 \$600.00           |
| 1        | REAR BUMPER LOWER PAD KIT <i>giond/70cm</i>      | 241.30 \$290.00           |
| 2        | REAR BUMPER REFLECTOR L-R @95 <i>N/S 110/5cm</i> | 82.50 \$190.00 <i>1pc</i> |
| 2        | REAR BUMPER BRACKET L-R @80 <i>11</i>            | \$160.00 <i>X</i>         |
| 1        | REAR BUMPER CLIP @6.50 <i>1el</i>                | 35.00 \$65.00             |
| 1        | REAR BUMPER <i>Beam</i> <i>DD</i>                | 294.80 \$370.00           |
| 1        | REAR END PANEL <i>DD/3ent</i>                    | 454.60 \$550.00           |
| 1        | REAR END PANEL INNER BOARD <i>SU</i>             | \$350.00 <i>X</i>         |
| 1        | REAR BOOTLID <i>DD/3ent</i>                      | \$950.10                  |
| 1        | REAR BOOTLID GARNISH <i>MS</i>                   | \$185.60 <i>X</i>         |
| 2        | REAR BOOT INNER LOCK TOP & BOTTOM LOCK <i>SU</i> | \$255.70 <i>X</i>         |
| 1        | REAR BOOT LAMP L-R @870 <i>11</i>                | \$1,740.00 <i>X</i>       |
| 1        | REAR BOOT EMBLEM <i>SU</i>                       | \$50.00 <i>X</i>          |
| 1        | REAR BOOT LOGO <i>Repatch</i>                    | \$65.00 <i>X</i>          |
| 2        | REAR BOOT 'ELANTRA' EMBLEM <i>Re</i>             | 48.00 \$65.00             |
| 2        | REAR BOOT 'S' EMBLEM <i>Re</i>                   | \$45.00                   |
| 1        | REAR BOOT WEATHER STRP <i>1m</i>                 | \$155.00                  |
| 1        | REAR TAIL LAMP L-H @620.00 <i>one</i>            | 580.00 <i>X 2 = 1160</i>  |
| 1        | REAR TAIL LAMP BRACKET L-H @125.00 <i>11</i>     | \$250.00 <i>X</i>         |
| 2        | REAR FENDER L-R @950 <i>11</i>                   | \$1,900.00 <i>X</i>       |
| 2        | REAR FENDER INNER TRIM BOARD L-R @310 <i>11</i>  | \$620.00 <i>X</i>         |
| 1        | REAR SPARE TYRE BOARD <i>11</i>                  | \$230.00 <i>X</i>         |
| TOTAL    |                                                  | \$10,326.40               |
| LESS 20% |                                                  | \$2,065.28                |
| TOTAL    |                                                  | \$8,261.12                |

| SPECIAL NETT ITEMS |                                            |                       |
|--------------------|--------------------------------------------|-----------------------|
| 1                  | REAR licence PLATE <i>11</i>               | \$55.00 <i>X</i>      |
| 1                  | REAR NUMBER PLATE BOX <i>11</i>            | \$120.00 <i>X</i>     |
| 1                  | REAR BUMPER REVERSE SENSOR <i>SU</i>       | \$350.00 <i>X</i>     |
| 1                  | REAR BUMPER CLIPS <i>Re</i>                | \$55.00 <i>30 S/N</i> |
| 1                  | REAR BOOT LID INNER SHEILD CLIPS <i>11</i> | \$50.00 <i>X</i>      |
| 1                  | REAR FENDER CLIPS <i>11</i>                | \$50.00 <i>X</i>      |
| 1                  | REAR TAIL LAMP CLIPS <i>11</i>             | \$30.00 <i>X</i>      |
| TOTAL              |                                            | \$710.00              |

#### LABOUR CHARGES

|                                                 |                     |
|-------------------------------------------------|---------------------|
| TO REMOVE AND REFIX REVERSE SENSOR              | \$100.00 <i>30</i>  |
| TO REMOVE AND REFIX EXHAUST BOX                 | 11 \$80.00 <i>X</i> |
| TO REMOVE, REFIT, REPLACE LAMP AND CHECK WIRING | \$80.00 <i>20</i>   |
| TO APPLY UNDERCOATING ON ACCIDENT PARTS         | \$450.00 <i>60</i>  |

To panel beating, replaced parts  
AND REPLACE RE-ALIGNMENT ON DAMAGED PARTS  
TO Putty & spray painting

\$1,500.00 600  
\$1000.00 - 600

TOTAL

**ESTIMATE PARTS AND LABOUR GRAND TOTAL**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 3950.50  
202  
p- 3600.40  
s.w 30  
2-1310  
4500.4  
207  
3600