(08/11/13)	wef	
		-

REF: CS/21P24100209 Unh3

ASS	IGNMENT			
From: Date:	Veh No: SM A \$ 87/R Yr Regn: 27/0/6/18			
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /			
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (#) 625			
To Inspect Vehicle No: SM A F& 7/R	Make: Hrunda's Elentro c.c 155/			
at Workshop m/s Sura Success	Colour A/C: Insured / Std / NI / NA			
of	Sp.Reading // Sp. T/Radio: Insured / Std / NI / NA			
Insured: SMY 7770A	Eng/No:			
Policy No.	C/NO: KMHD&41CMJU70547			
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt			
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or			
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or			
Make of Veh:	Modi: Nil / \$/Rim / STD A/Rim or			
	Tyre Size: F: 205/55-27/6			
(Policy Condition)	R:			
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /			
repair at the time of inspection.	TOYO / YOKO or			
Bal. or Market Value:	Front Rear			
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm			
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm			
Est. Repairs:	D.O.A. 08/10/24 D.O.I. 1/1/13/24			
Lum Sum: % 3 Val.: Yes or No	Survey held at			
CA / REV / REP. / 24 HRS 9366	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or			
Vehicle: IN / OUT				
Date: Person Contacted: 174 (2) 40]	The U/C / Chassis frame / Body Structure affected due to collision.			
Date / Time Action / Instruction ACTION ASSOCIATION ACTION ASSOCIATION ACTION ACTIO	AH huaf (Red. \$ 8581.12, 70%)			
Date/Time, File Pass to? : Preli. Report : Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee:			
1) : Final Report Date/Time, File Return to?	Transportation:			
2) Add Fe	e: : Site Insp (\$)s+Rs,si			
	: Interview (\$) Photos			
Report Format :	: Tech. Invs (\$) Others			
Lump Sum / I.B.I: (\$: Weekend (\$			

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Singapore NRIC 936C SMA8871R No 11 Oct 2024 HYUNDAI ELANTRA AD 1.6 GLS AT (AMS) Silver 2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp) \$12,232.00	
SMA8871R No 11 Oct 2024 HYUNDAI ELANTRA AD 1.6 GLS AT (AMS) Silver 2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
No 11 Oct 2024 HYUNDAI ELANTRA AD 1.6 GLS AT (AMS) Silver 2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
11 Oct 2024 HYUNDAI ELANTRA AD 1.6 GLS AT (AMS) Silver 2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
HYUNDAI ELANTRA AD 1.6 GLS AT (AMS) Silver 2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
ELANTRA AD 1.6 GLS AT (AMS) Silver 2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
Silver 2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
2018 G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
G4FGJU207260 KMHD841CMJU705470 93.8 kW (125 bhp)	
KMHD841CMJU705470 93.8 kW (125 bhp)	
93.8 kW (125 bhp)	
\$12,232.00	
22 Jun 2018	
22 Jun 2018	
0	
\$12,232.00 616	
Yes	
21 Jun 2028	
\$7,950.00	
21 Jun 2028	
A - Car up to 1600cc & 97kW (130bhp)	
10	
\$36,426.00	
\$13,457.00	
\$21,407.00	

The information contained herein is correct as at 11 Oct 2024

sgcarmart





\$54,800 \subseteq \$11,970 /yr \infty \frac{31-Oct-2018}{(4yrs COE left)} \frac{98,000 kmk}{31,591 cc} \tag{1,591 cc} Hyundai Elantra 1.6A GLS S We are highly reviewed on google and Facebook! Agent maintained, 1 year

comprehensive warranty provided! \$0 driveaway available from our own in house loan, instant same day loan approval! High trade in valuation for your car!

Posted 10-Oct-2024

Compare

EURO SUCCESS SERV PTE. LTD 1 KAKIT BUKIT AVE 6, #02-03 SINGAPORE 417883

TEL: 67426231

FAX: 67411019

Not Arthurst 45 # 3600 neas 4 days.

H/P: 98289277 (Ah Huat)

Vehicle No: SMA 8871R

Model: HYUNDAI ELANTRA

			44011	NT.
QTY		LIST ITEMS	AMOUI	
1		REAR BUMPER 70CA	484.20	\$600.00
1		REAR BUMPER LOWER PAD KIT SION / TOIN	241.30	\$290.00
2		REAR BUMPER REFLECTOR L-R @95 N/Sna 0/5020	85.00	\$190.00 126
2		REAR BUMPER BRACKET L-R @80 4 1		\$160.00 X
1		REAR BUMPER CLIP @6.50	35,00	\$65.00
1		REAR BUMPER Seem DD	294.80	\$370.00
1		REAR END PANEL PO / Sat	454.60	\$550.00
1		REAR END PANEL INNER BOARD SU		\$350.00 ×
1		REAR BOOTLID 20/34		\$950.10
1		REAR BOOTLID GARNISH		\$185.60 ×
2		REAR BOOT INNER LOCK TOP & BOTTOM LOCK Suc	/	\$255.70 🗶
1		REAR BOOT LAMP L-R @870 41		\$1,740.00 🗶
1		REAR BOOT EMBLEM SU,		\$50.00 🗴
1		REAR BOOT LOGO Republic		\$65.00 ×
2		REAR BOOT 'ELANTRA' EMBLEM	48.00	\$65.00
2		REAR BOOT 'S' EMBLEM		\$45.00
1		REAR BOOT WEATHER STRP 121		\$155.00
1			580. X 2 = 7/60	\$1,240.00
1		REAR TAIL LAMP BRACKET L-H @125.00 11	1100	\$250.00 >
2		REAR FENDER L-R @950 ✓ ^		\$1,900.00 >
2		REAR FENDER INNER TRIM BOARD L-R @310 1		\$620.00 >
1		REAR SPARE TYRE BOARD A		\$230.00 ×
1		REAR SPARE TIME BOARD S(1)	TOTAL	\$10,326.40
			LESS 20%	\$2,065.28
			TOTAL	\$8,261.12
				5. (5.)
		SPECIAL NETT ITEMS		
1		REAR liceacy PLATE		\$55.00 y
1		REAR NUMBER PLATE BOX		\$120.00 🗴
1		REAR BUMPER REVERSE SENSOR		\$350.00 ×
1	cal	REAR BUMPER CLIPS	1	\$55.00 30 5/N
	set	REAR BOOT LID INNER SHEILD CLIPS 1		\$50.00 %
1				\$50.00 ×
1		NEAR LEITER.	et	\$30.00
1		REAR TAIL LAMP CLIPS ^^	TOTAL	\$710.00
			IOIAL	4, 20.00
		LAROUR CHARCES		
		LABOUR CHARGES		\$100.00 30
		TO REMOVE AND REFIX REVERSE SENSOR		^^ \$80.00 X
		TO REMOVE AND REFIX EXHAUST BOX	ING	\$80.00 20
		TO REMOVE, REFIT, REPLACE LAMP AND CHECK WIR		\$450.0060
		TO APPLY UNDERCOATING ON ACCIDENT PARTS		ψ.00.000 0

To pand beating, replaced parts
AND REPLACE RE-ALGINMENT ON DAMAGED PARTS
TO PUTTY & spray pointing

\$1,500.00 600 \$1000.00-600

TOTAL

ESTIMATE PARTS AND LABOUR GRAND TOTAL

12181.12

KK Auto Consultants hence nearly near Repairer of the following:

e 10 LOSHIVEA DEIDLESOLO COLCA Name

e to distray gamaged hands

e Parts prices are subject to contain auton

a Third party survey is on a "Without Projection" boost

No illugal modification(s) is allowed

Supplementary item(s) must be resumant designed in the supplementary item(s) must be resumant of the supplementary items of the supplementary i

Acknowledged by Repairer

Signature:

Distan

2-3950:50 202 2-360:40 SIN 30 4-1310 4500:4 2-1310