



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS HUI YANG MOTOR PTE LTD		Ref:	CS/TP24100210/Knh3m4	
BLK 176 SIN MING DRIVE		Date:	16/10/2024	
#04-02 SIN MING AUTOCARE SINGAPORE 575721		Code:	TP034	
ON BEHALF OF MUHAMAD NAUFAL BIN NOORDIN				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	-	Veh. Inspected	SNK 8113G	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	11/10/2024	
2. Vehicle Details				
Make & Model	TOYOTA RAIZE (A)	C.C	1196	
Engine No.	WA0035980	Year of Reg.	16/05/2023	
Chassis No.	A201A0002819	Colour	METALLIC RED	
Odometer	40190 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	215/55R17	HANKOOK	7	
L/H Front Tyre	215/55R17	HANKOOK	7	
R/H Rear Tyre	215/55R17	HANKOOK	7	
L/H Rear Tyre	215/55R17	HANKOOK	7	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/10/2024	Inspection Date	08/10/2024	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				