

TSL AUTO PRO SELECTION PTE LTD

BLK 1 KAKI BUKIT AVE 6 #01-06 AUTOBAY @KAKI BUKIT
SINGAPORE 417883

Nett Value: 6K

TO	: NTUC	DATE	11/10/2024
VEHICLE NO	: SLX6967C (2015)		Xiao Chen.
VEHICLE MODEL	: NISSAN QASHQAI		
CHASSIS NO	: SJNFBAJ11U1459682		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Dented</i>	1	\$ 682.90	\$ 682.90
2	FRONT BUMPER SIDE HOLDER <i>new</i>	1	\$ 32.10	\$ 32.10
3	FRONT BUMPER FOG LAMP <i>cracked</i>	1	\$ 342.10	\$ 342.10
4	FRONT BUMPER FOG LAMP COVER <i>new</i>	1	\$ 75.10	\$ 75.10
5	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 182.60	\$ 182.60
6	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 337.30	\$ 337.30
7	HEADLAMP <i>cracked</i>	1	\$ 2,365.70	\$ 2,365.70
8	FRONT GRILLE <i>3 HP</i>	1	\$ 525.40	\$ 525.40
9	FRONT GRILLE LOGO <i>new</i>	1	\$ 78.20	\$ 78.20
10	FRONT FENDER <i>Dented</i>	1	\$ 677.10	\$ 677.10
11	FRONT FENDER INNER SHIELD <i>torn</i>	1	\$ 195.80	\$ 195.80
12	FRONT FENDER ARC GARNISH <i>missing</i>	1	\$ 483.80	\$ 483.80
13	FRONT WHEEL RIM <i>cut</i>	1	\$ 1,866.10	\$ 1,866.10
14	FRONT LOWER ARM <i>2</i>	1	\$ 546.80	\$ 546.80
15	FRONT KNUCKLE ARM <i>3 HP</i>	1	\$ 598.60	\$ 598.60
16	FRONT WHEEL HUB C/W BEARING <i>HP</i>	1	\$ 398.60	\$ 398.60
17	FRONT SHOCK ABSORBER <i>HP</i>	1	\$ 493.80	\$ 493.80
18	STEERING RACK & PINION <i>HP</i>	1	\$ 1,850.90	\$ 1,850.90
19	FUSE BOX <i>cracked</i>	1	\$ 445.70	\$ 445.70
20	BONNET <i>Dented</i>	1	\$ 1,061.30	\$ 1,061.30

TOTAL PRICE: \$ 13,239.90

LESS 10% \$ 1,323.99

SUB TOTAL PRICE: \$ 11,915.91

6437
579330 S.N: 650

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT GRILLE CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	FRONT FENDER INNER SHIELD CLIPS <i>3 HP</i>	1 SET	\$ 30.00	\$ 30.00
4	FRONT FENDER ARC GARNISH CLIPS <i>HP</i>	1 SET	\$ 20.00	\$ 20.00
5	FRONT TYRE <i>HP new</i>	1	\$ 280.00	\$ 280.00

TOTAL: \$ 380.00

80

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	X	
5	TO REMOVE FRONT UNDERCARRIAGE	\$ 380.00	X	
6	TO REMOVE STEERING RACK & PINION	\$ 180.00	X	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	

TOTAL: \$ 2,910.00

1310

ESTIMATE REPORT

TOTAL PARTS COST: \$ 12,295.91

TOTAL LABOUR COST: \$ 2,910.00

TOTAL REPAIR COST: \$ 15,205.91

Total: 7833.3k.

C/S: GK (Nett Value)

0.5 Days. ✓



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: