

ESTIMATED ACCIDENT REPAIR COST



Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	15:11 HRS
ACCIDENT DATE	9-Oct-24
BUS CAPTAIN NAME	TAN LEONG GUAN
THIRD PARTY CLAIM AGAINST	SMRT

BUS REGISTRATION NUMBER	SBS3363J
BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	REAREND AIRCON DOOR <i>bt</i>	1	\$ 6,178.28
2	REAR ENGINE SERVICE <i>bt</i>	1	\$ 6,037.66
3	BOTTOM BOOT DOOR ASSEMBLY <i>bt</i>	1	\$ 2,756.31
4	EXT DOOR CAPPING PANEL <i>Xm</i>	1	\$ 307.65
5	NO PLATE RECESS PAN <i>cm</i>	1	\$ 182.34
6	HYDRAULIC FLUID TANK <i>cm</i>	1	\$ 1,163.56
7	HYDRAULIC FLUID <i>m</i>	38L 25L	\$ 429.60 600.60
8	ENGINE BAY LIGHT SOC <i>cm</i>	1	\$ 464.31
9	LICENSE PLATE LIGHT OLD <i>cm</i>	1 A	\$ 22.66 45.32
10	TOWER TRANSIT LOGO (B) <i>m</i>	1	\$ 66.00
		9% GST	\$ 1,602.18
		PARTS TOTAL COST	\$ 19,404.21

17300.12

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • DISMANTLE AND REPLACE ITEM NO :1-10	3250 \$ 6,500.00
SPRAY PAINTING :- • REAR END AIRCON DOOR • REAR ENGINE SERVICE DOOR • BOTTOM BOOT DOOR ASSY • EXT DOOR CAPPING PANEL • NO PLATE PAN	5810 2560 \$ 3,200.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	9% GST \$ 873.00
	LABOUR TOTAL COST \$ 10,573.00

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	9/Oct/2024	
		DATE & TIME SURVEY		
		DATE OUT		
		TOTAL NUMBER OF DAYS	9	
BUS TYPE (SD / DD)	DD	LOSS OF USE COST		\$3,600.00

SUMMARY	
SECTION NO.	COST
1	\$ 19,404.21
2	\$ 10,573.00
3	-
4	\$ 3,600.00
TOTAL	\$ 33,577.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

17300112

5810100

23/10/12

Rasue

Hp 9001268

8 days

11/10/24

Res by paint