



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNA 8200R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BOOTLID	TO REPAIR SEE LABOUR	\$2,998.20	\$0.00
1	BOOTLID REAR LOGO	NECESSARY	\$99.40	\$99.40
1	BOOTLID 9 G-TRONIC EMBLEM	NECESSARY	\$75.00	\$75.00
1	BOOTLID C 180 EMBLEM	NECESSARY	\$92.00	\$92.00
1	BOOTLID C&C LOGO	NECESSARY	\$30.00	\$30.00
1	BOOTLID WEATHERSTRIP	TWISTED	\$282.20	\$282.20
1	BOOTLID INNER LOCK	SERVICEABLE	\$324.41	\$0.00
1	REAR BUMPER	DENTED	\$1,910.68	\$1,910.68
1	REAR BUMPER LOWER GARNISH	TWISTED/DEFORMED	\$455.80	\$455.80
1	REAR BUMPER CENTRE CHROME MOULDING	SERVICEABLE	\$432.35	\$0.00
3	REAR BUMPER PDC SENSORS @\$195.00	SERVICEABLE	\$585.00	\$0.00
1	REAR BUMPER REINFORCEMENT	BENT	\$722.89	\$722.89
1	SET REAR BUMPER CLIPS & RIVERT	NECESSARY	\$60.00	\$60.00
2	REAR BUMPER SIDE HOLDERS @\$165.00	N/S CRACKED	\$330.00	\$165.00
1	REAR BUMPER KICKING SENSOR	DAMAGED/CRACKED	\$364.00	\$364.00
1	REAR BUMPER TOP RETAINER	CRACKED	\$158.20	\$158.20
1	REAR END PANEL	DENTED	\$913.70	\$913.70
1	TAILLAMP N/S	CRACKED	\$725.21	\$725.21
1	TAILLAMP SIDE BLACK GARNISH N/S	TORN	\$52.60	\$52.60
	LESS 10.00% DISCOUNT		(\$1,061.16)	(\$610.67)
			\$9,550.48	\$5,496.01

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING		\$50.00	\$20.00
	TO DISMANTLE & REFIX REAR PDC SENSOR		\$80.00	\$30.00
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY		\$120.00	\$60.00
	TO TRANSFER BOOTLID MECHANISM	NOT NECESSARY	\$100.00	\$0.00
	TO DISMANTLE & REFIX REAR EXHAUST	NOT NECESSARY	\$100.00	\$0.00
	TO SPRAY RUST PROOFING		\$90.00	\$30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RESET & REPROGRAMME SYSTEM	NOT NECESSARY	\$100.00	\$0.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID		\$900.00	\$600.00
	TO PUTTY & SPRAY PAINTING		\$1,580.00	\$800.00
			\$3,120.00	\$1,540.00
GRAND TOTAL			\$12,670.48	\$7,036.01
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,600.00
Report Ref No: CS/SMO24100215/Uvp3e2				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.