

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not Authorised
an
meas
11/10/24
1/57 \$5600
the photo. After -
5 days.

VEHICLE No: SNA 8200R

1PC	BOOTLID	R	\$2,998.20 X
1PC	BOOTLID REAR LOGO	NEC	\$99.40 /
1PC	BOOTLID 9 G-TRONIC EMBLEM	NEC	\$75.00 /
1PC	BOOTLID C 180 EMBLEM	NEC	\$92.00 /
1PC	BOOTLID C&C LOGO	NEC	\$30.00 /
1PC	BOOTLID WEATHERSTRIP	NEC	\$282.20 /
1PC	BOOTLID INNER LOCK	NEC	\$324.41 X
1PC	REAR BUMPER	NEC	\$1,910.68 /
1PC	REAR BUMPER LOWER GARNISH	NEC	\$455.80 /
1PC	REAR BUMPER CENTRE CHROME MOULDING	NEC	\$432.35 X
3PCS	REAR BUMPER PDC SENSORS @\$195.00	NEC	\$585.00 X
1PC	REAR BUMPER REINFORCEMENT	NEC	\$722.89 /
1SET	REAR BUMPER CLIPS & RIVERT	NEC	\$60.00 /
2PCS	REAR BUMPER SIDE HOLDERS @\$165.00	NEC	\$330.00 1PC
1PC	REAR BUMPER KICKING SENSOR	NEC	\$364.00 /
1PC	REAR BUMPER TOP RETAINER	NEC	\$158.20 /
1PC	REAR END PANEL	NEC	\$913.70 /
1PC	TAILLAMP N/S	NEC	\$725.21 /
1PC	TAILLAMP SIDE BLACK GARNISH N/S	NEC	\$52.60 /
			\$10,611.64
LESS 10%			\$9,550.48

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & ^{refix} REPLACED REAR PDC SENSOR	\$80.00 30
TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	\$120.00 60
TO TRANSFER BOOTLID MECHANISM	NEC \$100.00 X
TO DISMANTLE & REFIX REAR EXHAUST	NEC \$100.00 X
TO SPRAY RUST PROOFING	\$90.00 30
TO RESET & REPROGRAMME SYSTEM	NEC \$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$900.00 600
TO PUTTY & SPRAY PAINTING	\$1,580.00 800
TOTAL	\$12,670.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6106.68
202
5496.01
1540
7036.01
202
5628.