

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BAK HOE
BLK 186 PUNGGOL CENTRAL #06-257
SINGAPORE 820186

Contact : 91069970

TP Budget Direct
Xiao Chen.

TAX INVOICE

Repair Code : CLM16336

Date in : 22/06/2024

Vehicle Num. : SKZ9827E

Model : RENAULT KADJAR 1.5 DCI EDC 6AT S&S SR EU6

Chassis/Eng# : VF1RFE00654465058/K9KF647D014435

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Disturbed</i>	1	1975.00	<i>1710</i> 1975.00
REAR BUMPER LOWER BRACKET <i>assembled</i>	1	92.00	<i>✓</i> 92.00
REAR BUMPER LOWER DIFFUSER <i>Disturbed</i>	1	547.00	<i>✓</i> 547.00
REAR BUMPER REINFORCEMENT <i>Disturbed</i>	1	499.00	<i>✓</i> 499.00
REAR BUMPER REVERSE SENSOR 'O' RING L/R <i>new 1 piece</i>	4	25.00	<i>25</i> 100.00
REAR BUMPER REVERSE SENSOR HOLDER L/R <i>new</i>	4	35.00	<i>✓</i> 140.00
REAR BUMPER REVERSE SENSOR L/R <i>1 piece damaged</i>	4	212.00	<i>212</i> 848.00
REAR BUMPER RH REFLECTOR <i>could</i>	1	187.00	<i>✓</i> 187.00
REAR BUMPER SIDE L/R <i>Rlt Disturbed</i>	2	398.00	<i>398</i> 796.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	177.00	<i>+</i> 354.00
REAR BUMPER TOW HOOK COVER <i>new</i>	1	70.00	<i>+</i> 70.00
REAR END PANEL <i>Disturbed</i>	1	1035.00	<i>890</i> 1,035.00
REAR END PANEL ANTENNA SENSOR <i>could</i>	1	170.00	<i>✓</i> 170.00
REAR END PANEL INNER TOP GARNISH <i>Disturbed</i>	1	307.00	<i>✓</i> 307.00
REAR EXHAUST GASKET <i>2</i>	1	87.00	<i>+</i> 87.00
REAR EXHAUST RUBBER MOUNTING <i>2</i>	1	95.00	<i>+</i> 95.00
REAR EXHAUST SILENCER BOX <i>2</i>	1	1775.00	<i>+</i> 1,775.00
REAR RH TAILLAMP <i>Not new</i>	1	1170.00	<i>X</i> 1,170.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BAK HOE
BLK 186 PUNGGOL CENTRAL #06-257
SINGAPORE 820186

Contact : 91069970

TAX INVOICE

Repair Code : CLM16336

Date in : 22/06/2024

Vehicle Num. : SKZ9827E

Model : RENAULT KADJAR 1.5 DCI EDC 6AT S&S SR EU6

Chassis/Eng# : VF1RFE00654465058/K9KF647D014435

REAR TAILGATE <i>Dented</i>	1	2895.00	✓	2,895.00
REAR TAILGATE 'ECO0' EMBLEM	1	147.00	✓	147.00
REAR TAILGATE 'KADJAR' EMBLEM <i>3</i>	1	217.00	✓	217.00
REAR TAILGATE 'LOGO' EMBLEM	1	185.00	✓	185.00
REAR TAILGATE 'RENAULT' EMBLEM <i>for</i>	1	166.00	✓	166.00
REAR TAILGATE CAMERA <i>new</i>	1	1076.00	+	1,076.00
REAR TAILGATE DAMPER L/R <i>new</i>	2	195.00	+	390.00
REAR TAILGATE HINGES L/R <i>new</i>	2	137.00	+	274.00
REAR TAILGATE INNER LOWER GARNISH <i>cracked</i>	1	187.00	✓	187.00
REAR TAILGATE INNER RUBBER STOPPER L/R <i>new</i>	2	45.00	+	90.00
REAR TAILGATE INNER TRIM BOARD <i>cracked</i>	1	979.00	780 ✓	979.00
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	373.00	✓	373.00
REAR TAILGATE NUMBER PLATE LAMP L/R <i>RH. cracked</i>	2	154.00	154 ✓	308.00
REAR TAILGATE OPENER SWITCH BOTTOM <i>new</i>	1	195.00	+	195.00
REAR TAILGATE REFLECTOR L/R <i>new</i>	2	517.00	+	1,034.00
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	277.00	✓	277.00
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	199.00	✓	199.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BAK HOE
BLK 186 PUNGGOL CENTRAL #06-257
SINGAPORE 820186

Contact : 91069970

TAX INVOICE

Repair Code : CLM16336

Date in : 22/06/2024

Vehicle Num. : SKZ9827E

Model : RENAULT KADJAR 1.5 DCI EDC 6AT S&S SR EU6

Chassis/Eng# : VF1RFE00654465058/K9KF647D014435

		Subtotal before discount	19,239.00
Percentage discount	10%	10757 9681.30	1,923.90
		Sub-total 1	17,315.10
REAR BUMPER CLIPS - SET	1	50.00	50 50.00
REAR BUMPER NUMBER PLATE	1	25.00	x 25.00
REAR BUMPER NUMBER PLATE FRAME	1	50.00	x 50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	10 30.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	30 50.00
REAR TAILGATE LOWER CHROME MOULDING	1	250.00	100 250.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60 80.00
		Subtotal before discount	535.00
Percentage discount	0%		0.00
		Sub-total 2	535.00
		Parts-total	17,850.10

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

80.00
120 150.00
60 80.00
500 1,000.00
8 100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BAK HOE
BLK 186 PUNGGOL CENTRAL #06-257
SINGAPORE 820186

Contact : 91069970

TAX INVOICE

Repair Code : CLM16336

Date in : 22/06/2024

Vehicle Num. : SKZ9827E

Model : RENAULT KADJAR 1.5 DCI EDC 6AT S&S SR EU6

Chassis/Eng# : VF1RFE00654465058/K9KF647D014435

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

1480
1,000.00
80.00
80.00

Labour Total

2,570.00

Parts & Labour Total

20,420.10

*** This is a computer-generated document which requires no signature.***

page 4

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin
2/8 26/06/24

06 Days

Total: 11411.30

2/8: 7.1K ✓