

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI24100218/JVH3E2**Date:** 30/10/2024REFERENCE

Insured/Claimant:	NG SHI JIE	Policy No:	DMPCSNW00095282402		
Date of Loss:	07/10/2024	Nature of Claim:	OD	Claim No:	SNM24D205689/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH6969H		Engine No:	27191031352556
Make & Model:	MERCEDES-BENZ C180, 1.6 Kompressor (A)		Chassis No:	WDD2040452A679746
Reg. Date:	01/03/2012 (Man. Year: 2012)		Odometer:	0 km
Colour:	White			
Engine Capacity:	1597 cc			
Market Value/New Car Price:	S\$75,500.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	0 mm	Rear Left Side:	0 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	1,000.00	-1,000.00	
Nett Amount (S\$)	0.00	-1,000.00	1,000.00	

INSPECTION

Date of Assignment:	14/10/2024	5 Soon Lee Street, Pioneer Point #01-34 Singapore 627607
Date Inspected:	14/10/2024 Inspected At:	Repairer: Sng Ah Tee Motor & Panel Service Pte Ltd
Estimated Period of Repair:	0.0 days	

Adjuster: Elton**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$75,500.00
OMV :	\$30,319.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$56,670.00
COE Rebate (2) :	\$41,785.00
Total Rebate (1) + (2) = :	\$41,785.00

The total amount incurred will be Market Value \$75,500.00 minus Total Rebate \$41,785.00 = \$33,715.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts: 143	MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH6969H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >