



Your Ref : SNM24D205689/C02/TANCHC

Date: 30<sup>th</sup> Oct 2024

Our Ref : CS/CTI24100218/Jvh3e2

**M/s Chine Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SNH 6969H  
ACCIDENT ON 07/10/2024**

Instruction was received to inspect the vehicle Reg. No. SNH 6969H. The inspection was conducted on 14/10/2024 at 5 Soon Lee Street, Pioneer Point #01-34, Singapore 627607, Repairer: M/s Sng Ah Tee Motor & Panel Service Pte Ltd.

The following vehicle information was recorded:

Registration Number	: SNH 6969H
Make/Model	: Mercedes Benz C 180 Kompressor
Year of Registration	: 2012
Body Colour	: White
Chassis Number	: WDD2040452A679746
Engine Capacity	: 1597 cc
Speedometer Reading	: N/A

The vehicle caught fire. The cause of fire probably due to fluid fire. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 75,500.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 41,785.00)
Nett Liability	<u>S\$ 33,715.00</u> =====

Vehicle Inspected By:



ELTON SEET BOON KIAT  
*Asst. Automotive Assessor*



K.K.LAU  
*MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.