

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24100219/KPA3Q2**Date:** 06/02/2026**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0002377_04
Claimant Vehicle No : SMP6666B **Insured Vehicle No :** YP2281L
 Date of Loss: 11/10/2024 Nature of Claim: TP Claim No: MFL2024D0012187

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP6666B**
 Make & Model: TOYOTA ALPHARD, 2.5 HYBRID SR-C PACKAGE Engine No: 2AR2614571
 CVT (A)
 Reg. Date: 26/11/2021 (Man. Year: 2021) Chassis No: AGH300366692
 Colour: Metallic Pearl White Odometer: 83344 km
 Engine Capacity: 2493 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,029.20	1,184.85	2,844.35	70.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,010.00	440.00	30.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,479.20	2,194.85	3,284.35	59.94
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	5,479.20	1,750.00	3,729.20	68.06
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,277.25		
Global Sum Settlement (S\$)		2,250.00		

INSPECTION

Date of Assignment: 14/10/2024
 Date Inspected: 14/10/2024 Inspected At: Poon Siang Seow (HQ)
 160 Sin Ming Drive, #05-13 Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2024)
Parts: M1-MPV	TOYOTA ALPHARD 2.5 HYBRID SR-C PACKAGE CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMP6666B)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,335.50 F	*- FL
2	1		*REAR BUMPER RETAINER	Serviceable	113.90 F	*- FL
3	1		*TAIL LAMP	Broken	899.80 F	*899.80 FL
4	1		*REAR FENDER GLASS	Cut	680.00 F	*680.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,029.20	1,579.80
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	394.95
Total Parts (\$)	4,029.20	1,184.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND LEFT REAR FENDER WLS GLASS	New	150.00	100.00
2	PANEL BEATING	New	400.00	250.00
3	PAINTING	New	900.00	660.00
			Gross Labour Cost (\$\$)	1,450.00
				1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >