



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

WANG LI
BLK 331B Anchorvale Street
#08-557
Singapore 542331

Dear sir

Estimate cost of repair to vehicle no. SMP6666B

To supply

1. Rear bumper	2,335.50	X
2. Rear bumper retainer	113.90	X
3. Tail lamp	899.80	—
4. Rear fender glass	680.00	✓

Labour charges

To remove and left rear fender wls glass

Panel beating

Painting

Total

150.00
400.00
900.00
5,479.20

251

1001

2501

8601

Your faithfully

ALBERT POON

Not with out
Resurvey After Paint

4 days
11 Pm @ 1750/h

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: